



Telephone: 867-587-7205  
Fax: 867-587-2928

July 11, 2019

NorthwesTel Inc.  
Property Management Department  
P.O. Box 2727  
Whitehorse, YU Y1A 4Y4

**Attention: Glenn Bushell**

<b>File Number</b>	<b>S14L-005</b>
<b>Type of Operation</b>	<b>MISC.</b>
<b>Location</b>	Tower Site

Dear Glenn Bushell,

An inspection of the above noted operation was conducted on July 09, 2019 by Resource Management Officer II Jonathan Gillingham, Manager of Resource Management Trevor Bremner and Resource Management Officer I Bonnie Deschene.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions and the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-587-7205.

Sincerely,

Jonathan Gillingham  
Resource Management Officer II  
Department of Lands  
Sahtu

CC: Sahtu Land and Water Board  
Trevor Bremner – Manager of Resource Management – Sahtu Region



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	NorthwesTel Inc.	<b>Permit Expiry Date:</b>	August 01, 2019
<b>Land Use Permit No.</b>	S14L-005	<b>Previous Inspection:</b>	June 07, 2017
<b>Quarrying Permit No.</b>	N/A	<b>Inspection Date:</b>	July 09, 2019
<b>Contractor:</b>	N/A	<b>Subcontractor:</b>	N/A
<b>Location(s) Inspected:</b>	Tower Site		
<b>Current Stage of Operation:</b>	Project build completed		
<b>Program Modifications Approved:</b>	None		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected					
	Tower Site					
Location as Permitted	A					
Time as Permitted	A					
Equipment as Approved (Type & Size)	A					
Methods & Techniques	N/A					
Facilities	A					
Erosion (Control or Prevention)	A					
Chemicals	A					
Wildlife and Fisheries Habitat (Protection)	A					
Wastes	A					
Historical / Archaeological Sites	A					
Ecological Resources	A					
Fuel Storage	A					
Brush Disposal	N/A					
Restoration of Lands	N/A					
Permits	A					
Matters not Inconsistent	A					
Sections 12 to 19 T.L.U.R.	N/A					
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A					

**Tower Site:**

The tower site is very tidy, there is no debris or signs of any contamination or spills on site. Four double walled fuel tanks remain on site. There are no signs of damage on these tanks. All structures on this site are well maintained and show no concerns at this time. Helipad on site is well maintained. This site shows no signs of any concerns.

\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature

Date:	July 09, 2019	Permit #:	S14L-005	Page No:	1
-------	---------------	-----------	----------	----------	---




# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**Fuel Tanks and tower**





## ENVIRONMENTAL INSPECTION REPORT

Figure 2

Fuel tanks, tower, facilities



Figure 3

Larger solar panels

