



Telephone: 867-777-8907

Fax: 867-777-2090

March 18, 2022

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number G20H006
Type of Operation CAMPS
Location KM 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on March 17, 2022 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 10, 2022
Land Use Permit No.	G20H006	Previous Inspection:	February 17, 2022
Quarrying Permit No.		Inspection Date:	March 17, 2022
Contractor:	L.J.'s	Subcontractor:	
Location(s) Inspected:	KM 14.2		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection at the James Creek maintenance camp there was only 1 concern observed by the inspector.

The snow cat at the site is leaking hydraulic fluid and should be repaired or removed from the site. There is drip trays under 2 of the leaks but not under the one side where a bit of oil is on the ground. The workers at the site indicated they will clean up the spill and put a tray under the leaks.

The rest of the site is clean and in good order.

Representative Signature

Inspector's Signature




ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

