



Telephone: 867-777-8907

Fax: 867-777-2090

October 8, 2021

GNWT Department of Infrastructure
Bag Service #1, 106 Veterans Way
Inuvik, NT X0E 0T0

Attention: Mosiul Alam

File Number G20H006
Type of Operation CAMPS
Location Km 14.2

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on October 07, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	August 05, 2021
Land Use Permit No.	G20H006	Previous Inspection:	September 09, 2021
Quarrying Permit No.	68	Inspection Date:	October 07, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 14.2		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	James Creek Km 14.2				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

James Creek Km 14.2:

During the inspection at the James Creek maintenance camp on October 7, 2021 there was one concerns observed by the inspector.

In December 11, 2020 an email from AlecSandra MacDonald, Regulary Specialist with the Gwich'in Land and Water Board to GNWT INF, AlecSandra indicated that there are a number of files that required actions in 2021. The File G20H006 requires a plan for the landfarm material before the move to the new site can take place.

There are the two land farms with contaminated soil that are located at the back of the site that have not been removed. There are two pallets with envirobags placed at the edge of land farm containing unknown material in them, one is at the front of the site and one on the side road of the farm. Please submit a plan to GLWB and GNWT Department of Lands in regards to the land farms an what actiones will be taken with the contaminated soil.

The rest of the site was clean and in good order.



ENVIRONMENTAL INSPECTION REPORT

Representative Signature

Inspector's Signature




ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3




Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

