

Incident #	INC-2019-001-HUS-OA-2018-002	
Incident occurred on:	February 7, 2019	
OA/ACW #:	ACW-2018-003	
Operator:	Husky Oil Ltd.	
Location:	Slater River – H-64	
Summary of incident:	Inconsistent pressure reading/ leaking primary controls during accumulator function test. – No Injury	
Incident reported to OROGO by the operator on:	February 7, 2019	
Incident reported to NT-NU Spill Line (if required) on:	N/A	
Operator Follow-up Investigation Report:	Due: Feb. 14, 2019 Received: Feb. 14, 2019	
Status:	<p>Feb. 7, 2019: During an accumulator function test it was noted that accumulator was not operating as designed and that there was a leak at the primary accumulator controls.</p> <p>OROGO required all operations to cease until the issue could be rectified.</p> <p>Issue identified, repairs made and information provided to OROGO.</p> <p>OROGO approved commencement of operations.</p> <p>Feb. 14, 2019 Summary report was sent to OROGO for review.</p> <p>No further action required – Incident closed.</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.