

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Netla C-07	Operator:	Canadian Natural Resource Ltd.
Location of Inspection:	60 ° 46' 13"N 122° 46' 18" W	Access method:	Helicopter
Site Contractor:	N/A	Status:	Non-compliant suspended
Approval Info	ACW-2019-008-CNRL-C-07-WID0191 Variation # 2	WID:	0191
Date of Inspection	23-FEB-2022	H2S Site:	Yes

Summary of Inspection

Activity on site	N/A		
Conditions	Satisfactory (Y/N)	Comments	
Site Access	N	No wind indicator installed on site. (See Photo #2)	
Well Head Access	Y		
Signage	N	Well identification sign not secured to well head (See Photo #3)	
General Housekeeping	Y	No debris noted on site above snow cover.	
SCV Open and dead	Y	SCV glove test indicated no negative or positive pressure. (See Photo #3)	

Additional Site Hazards:

At the time of the inspection there was brush encroachment onsite restricting site access and sight lines from some directions limiting safe access to the site. There was no wind indicator installed on the site.

Section 5A of the *Well Suspension and Abandonment Guidelines and Interpretation Notes* states "All wellheads must be safely accessible for inspection and monitoring".

The well site must allow for year-round access to inspect and monitor including winter months when there may be significant snow depth on the ground. This includes the requirements to install a wind indicator.

The placement of a nitrile glove over the Surface Casing Vent (SCV) indicated no positive or negative pressure.

Comments and Summary:

Aside from the issues mentioned above, the installed well head valve handles were chained and locked with some handles removed to prevent tampering. The well head identification sign was not secured in place and therefore, not compliant with the *Well Suspension and Abandonment Guidelines and Interpretation Notes*.

Documents Requested/ Collected:

N/A

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 and C-004 / Brian Heppelle S-001/C-005

Inspected By

Signature of OROGO Chief Safety Officer

18-MAR-2022

Date Signed



Photo #1: Aerial view of Netla C-07



Photo #2: Well head Netla C-07 – No wind indicator – Brush encroachment on wellhead



Photo #3: Netla C-07 - Well head identification sign not secured - Surface casing vent glove test