

From: [Ken Nikiforuk](#)
To: [DST_JUS_OROGO](#)
Subject: Fwd: IR2 - ACW-2022-SOG-B-25-WID1756
Date: August 22, 2022 4:18:15 PM
Attachments: [2022-08-08 - IR2 - Updates to Cameron B-25 Abandonment Program \(WID 1756\).docx.pdf](#)

EXTERNAL: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender's name and email address and know the content is safe.

Good afternoon

In response to the IR#2 for the B-25 ACW, a further wellfile review was performed.

It was confirmed that on March 24, 2007, there was a plug set in the R nipple at 1376.0 mKB as well as a shallow plug set in a slip stop in the tubing at 103.0 mCF. There was no plug placed at surface.

The existing shallow plug (103.0 mCF) removal procedures are detailed in steps 18 to 20 of the revised ACW submitted in response to IT#1.

It would appear that the confusion is created on the existing downhole diagram and the manner in which the dognut is represented at surface.

To confirm, there is no plug at surface.

If an updated existing downhole schematic is required, please let me know and it will be submitted.

Thanks, please get back to me with any questions or concerns.

Thanks

Ken N