
OROGO Well Abandonment Verification Inspection Summary Report

Well Information

Well name/ Facility: Cameron K-74

4 digit WID/ Facility Name: 1972

Operator: Strategic Oil and Gas Ltd.

Well status: Abandoned

Coordinates (*NAD 83; decimal degrees; verified onsite*)

Lat: N60.06142°

Long: W117.49233°

Inspection Date and Contact Information

Date of inspection: 2024-09-18

Access method: Helicopter

OROGO Inspector(s): Brandon Bradbury –
Technical Specialist/Conservation Officer

Activity Inspected

OA#: OA-2018-003-SOG

ACW# (If applicable): ACW-2023-SOG-K-74-
WID1972

Contractor on site: N/A

Name:

Company:

Phone:

Email:

Inspection Results

Site – Safety/Environment

Equipment, infrastructure or debris on site found during inspection?

Yes No

If yes, provide details: Surface debris was collected on site by Inspectors and consolidated by a section of casing which can be viewed in Photo #4.

Lease entrance sign was also still resent and must be removed for proper offsite disposal along with any other hazard or identifying signage that may be still present in the land use area. (Photo #5)

Additional clean up required? Yes No

If yes, provide details: There was only 1 large section of casing that was found approximately 30m west of the gravel pad where the helicopter landed, and various debris and waste was collected throughout the site by Inspectors and consolidated at this location. The waste viewed in Photo #4 must be removed for proper offsite disposal.

Version: October 15, 2024

Earth works related to decommissioning of facilities and infrastructure posing risk to public safety or the environment identified during inspection?

Yes No

If yes, provide details:

Well center appears not to have been backfilled as part of the well abandonment operations (Photo #3)

Contamination associated with historic or decommissioning operations identified during inspection?

Yes No

If yes, provide details:

Photographs

Number of photographs attached: 5

Additional Comments / Observations

As per OROGO's notice on September 25, 2024, temporary mitigation is required to be complete prior to October 31, 2024. Additionally, a plan to address the permanent mitigation of this excavation is required to be submitted to OROGO no later than December 15, 2024

This inspection was conducted under the *Oil and Gas Operations Act* and associated regulations.

Name: Brandon Bradbury

Name:

Designation: Technical Specialist/Conservation Officer

Designation:

ID number:

ID number:

Date: 2024-10-25

Date: Click or tap to enter a date.

Signature:



Signature:

Photographs



Photo #1. Aerial view of the K-74 well site facing south.



Photo #2. Another view of the K Camp laydown and K-74 wellsite towards the north. Helicopter landed on the gravel in the center of the camp laydown for reference.



Photo #3. It appears this sign may fall down in the future since it was very unstable upon inspection.



Photo #4. Various waste items were collected by Inspectors and consolidated by this large piece of casing approximately 30 meters west of the gravel pad.



Photo #5. Lease entrance sign remains on site and must be removed for proper offsite disposal.