

WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	Swede G-21	Operator:	Strategic Oil and Gas Ltd. (SOG)
Location of Inspection:	Cameron Hills	Access method:	Helicopter
Site Contractor:	None	Status:	Compliant Suspended – Exploratory Well
Approval Info	OA-2018-003	WID:	1764
Date of Inspection	10/SEP/2020	H2S Site:	Yes

Summary of Inspection

Activity on site		
Conditions	Satisfactory (Y/N)	Comments
Site Access	N ¹	<p>There were no wind indicators at the wellhead. To ensure safe access, wind indicators must be installed (See Photo #1).</p> <p>1. Section 5A of the Well Suspension and Abandonment Guidelines and Interpretation Notes requires that wells must be safely accessible for inspection and monitoring.</p>
Wellhead Access	N ²	<p>Three well head valves were not secured. (See Photo #1)</p> <p>Detached valve handles left on ground and in conductor hole. (See Photo # 2).</p> <p>2. Section 5A of the Well Suspension and Abandonment Guidelines and Interpretation Notes requires that valve handles must be chained and locked or, as an alternative, valve handles may be removed</p>
Signage	N ³	<p>Incorrect 24hr emergency contact number on well sign. (See Photo #3)</p> <p>3. The sign should include an emergency 24 hour contact number of the current owner/operator.</p>
General Housekeeping	Y	
SCV Open and dead	Y	0 bubbles observed in 10 minutes.

Additional Site Hazards:

Potential of H2S gas exposure, personal monitors worn by inspectors.

Comments and Summary:

OROGO Inspection Team: Michael Martin (Chief Safety Officer) and Brian Heppelle (Safety Officer/Conservation Officer)

Documents Requested/ Collected:

Photos and notes taken on site.

Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.

Michael Martin S-004 / Brian Heppelle S-001

Inspected By



Signature of OROGO Chief Safety Officer

September 29, 2020

Date Signed



Photo #: No wind indicator on well site. Wind indicator should be installed on well site. All well head valves should be secured to prevent unauthorized operation.



Photo #2: Detached valve handles left on ground and in conductor hole.



Photo #3: Incorrect 24hr emergency contact number on well sign.