



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Chinook Energy Inc.	Permit Expiry Date:	December 31, 2005
Land Use Permit No.	G2002A0011	Previous Inspection:	September 09, 2014
Quarrying Permit No.		Inspection Date:	September 25, 2015
Contractor:		Subcontractor:	
Location(s) Inspected:	Chinook C- 36		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Tree river c 36
Ecological Resources	A
Equipment as Approved (Type & Size)	A
Erosion (Control or Prevention)	A
Facilities	A
Location as Permitted	A
Matters not Inconsistent	A
Methods & Techniques	A
Restoration of Lands	A
Sections 8 to 12 / 14 to 16	A
M.V.L.U.R.	
Time as Permitted	A
Wildlife and Fisheries Habitat (Protection)	A

Explanatory Remarks -

Tree river c 36:

During the inspection it is evident that pooling is still occurring given the area surrounding the site and the high precipitation over the summer season. The reapplying and coconut matting placed in appears to be holding with no observed indication of any subsidence to the area. It was anticipated for the water to flow through the sump and the diversions made during the reclamation is doing as required to direct the majority of the flow to the outer perimeters of the sump. Inspectors are satisfied with the work done so far to control the flow and recommends that sampling be done next season to ensure contents are intact in the sump prior to recommending closure.

N/A

Representative Signature

[Signature]

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial of site



Figure 2

aerial of recap and coconut matting with water flow



Figure 3
coconut matting with water flow



Figure 4
bermed area to reduce flow of water

