



Telephone: 867 777-8900

Fax: 867-777-2090

February 20, 2018

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT X0E 0T0

Attention: Jahangir Hossain

File Number: G14E002
Type of Operation: QUARRY SITE - Existing
Location: Km 235 Quarry

To: Jahangir Hossain,

An inspection of the above noted operation was conducted on February 20, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF January 30, 2018

Ensure Pre data is provided prior to blasting.

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	January 30, 2018
Quarrying Permit No.		Inspection Date:	February 20, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 235 Quarry		
Current Stage of Operation:	ongoing		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 235				
Chemicals	A				
Historical / Archaeological Sites	A				
Erosion (Control or Prevention)	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	U				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Location as Permitted	A				
Time as Permitted	A				

Explanatory Remarks -

During this inspection it was observed that blasting was completed and crushing is now in progress, observed that the crushed material is being stock piled at the east side of the pit floor.

Please note that during the last inspection it was requested that the pre surveyed data be provided prior to any blasting, this is to inform that this data has not been received.

The unsatisfactory given here is for the following;

Inspector would like to bring to your attention that not only are the Terms and Conditions of your Land Use Permit are to be complied with, but also the Terms and Conditions of your quarry permit of which item number 8 states "Pre-surveys must be submitted to the land use inspector, 10 days prior to the commencement of operations, for approval."



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

Ensure Pre data is provided as per item 8 of the quarry permit.

N/A

Representative Signature

Inspector's Signature

Date:	February 20, 2018	Permit #:	G14E002	Page No:	2
-------	-------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7

