



Telephone: 867 777-8900

Fax: 867-777-2090

January 19, 2018

GNWT Department of Infrastructure  
Bag Service #1  
Inuvik, NT X0E 0T0

Attention: **Jahangir Hossain**

**File Number** G14E002  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 235

Dear Jahangir Hossain,

An inspection of the above noted operation was conducted on January 18, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Sincerely,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Dept. of Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF October 12, 2017

Ensure Pre and Post Data are provided.

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	May 24, 2019
<b>Land Use Permit No.</b>	G14E002	<b>Previous Inspection:</b>	October 12, 2017
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	January 18, 2018
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 235		
<b>Current Stage of Operation:</b>	Existing - on going		
<b>Program Modifications Approved:</b>	New QP issued		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 235</b>				
Location as Permitted	U				
Time as Permitted	U				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

**Km 235:**

During this inspection it was observed at the entrance to the site off the R.O.W. a gate had just finished being installed. Please note that the area of installation is on Territorial Lands and Department of Lands was not notified of this matter previously. Please note that any work outside of the scope of work on your Land Use Permits on Territorial Lands the Department of Lands Shall be notified for approval as per regulations.

The work and blast area was discussed with Wes Bergeron the foreman/site supervisor for Bobs Welding in regards to the work location (attached edited photo). It is understood at this time that 15000 cm will be taken from the location of which will be done in different stages with benches in place. Once the blast is completed the blast rock will be crushed and stock piled at the easterly side of the site for upcoming maintenance to the highway. It was further discussed that the pre and post data are to be provided, pre data will be provided once drilling is complete and the post data



## ENVIRONMENTAL INSPECTION REPORT

supplied after blast clean up is done.

The Unsatisfactory's given are for the following reasons- Installation of the fence is not part of the scope of work in the accepted application and Not informing the Department of Lands that work has commenced.

### MATTERS FOR FOLLOW UP

Ensure Pre and Post data are provided as per Quarry Permit Conditions.

N/A

Representative Signature

Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Gate



Figure 2







# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

Edited work location



Date:	January 18, 2018	Permit #:	G14E002	Page No:	4
-------	------------------	-----------	---------	----------	---