



Telephone: 867 777-8900
Fax: 867-777-2090

October 13, 2017

GNWT Department of Infrastructure
Bag Service #1
Inuvik, NT XOE OT0

Attention: Jahangir Hossain

File Number G14E002
Type of Operation QUARRY SITE - Existing
Location Km 06

To Jahangir Hossain,

An inspection of the above noted operation was conducted on October 12, 2017 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Dept. of Lands, Beaufort Delta Region
GLWB

ENVIRONMENTAL INSPECTION REPORT

Permittee:	GNWT Department of Infrastructure	Permit Expiry Date:	May 24, 2019
Land Use Permit No.	G14E002	Previous Inspection:	July 12, 2017
Quarrying Permit No.		Inspection Date:	October 12, 2017
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 06		
Current Stage of Operation:	on-going		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Dempster Highway				
Equipment as Approved (Type & Size)	A				
Location as Permitted	U				
Time as Permitted	U				
Erosion (Control or Prevention)	A				
Wildlife and Fisheries Habitat (Protection)	A				
Restoration of Lands	A				
Permits	U				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Methods & Techniques	A				
Chemicals	U				
Facilities	U				

Explanatory Remarks -

Dempster Highway:

During the inspection it was observed that activity was occurring at Km 06 where a crusher and stock piles was observed.

There is an estimated 1500 to 2500cm stockpiled at the location.

Department of Lands was not informed of this activity, therefore given the unacceptable for not informing the Dept. of Lands of start up at the location and not possessing a valid quarry authorization and quarry permit to do any crushing at Km. 06, this is also not within the scope of work under the current L.U.P.

Further unacceptables observed are the blue plastic oil containers are to be 100 meters away from a water source as there is a creek just below where they are stored. Also observed at the side of road there is debris that is to be picked up and removed.



ENVIRONMENTAL INSPECTION REPORT

MATTERS FOR FOLLOW UP

Ensure crushing is ceased and valid quarry authorization and permits are obtained.

N/A
Representative Signature

[Signature]
Inspector's Signature

Date:	October 12, 2017	Permit #:	G14E002	Page No:	2
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4
oil containers to close to creek below





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6
Garbage/Debris



Date:	October 12, 2017	Permit #:	G14E002	Page No:	5
-------	------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

