



Telephone: 867 777-8900

Fax: 867-777-2090

March 22, 2018

Arctic Tire (1980) Ltd
P.O. Box 3190
Inuvik, NT X0E 0T0

Attention: Brian McCarthy

File Number	G14Q003
Type of Operation	QUARRY SITE - Existing
Location	Km 251

To: Brian McCarthy,

An inspection of the above noted operation was conducted on March 21, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region

GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF March 05, 2018
 Permittee to provide full amounts removed from site.

Permittee:	Arctic Tire (1980) Ltd	Permit Expiry Date:	June 22, 2019
Land Use Permit No.	G14Q003	Previous Inspection:	March 05, 2018
Quarrying Permit No.		Inspection Date:	March 21, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	Complete		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Time as Permitted	U				
Facilities	A				
Restoration of Lands	U				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -
Km 251:

No change since previous inspection dated March 06, 2018.

Please note that this is a second request to provide full amounts removed from the site at km 251 and would like to bring to your attention that as per your quarry permit conditions the following items are still to be complied with.

12. Prior to the tenth of each month, the Permittee shall submit a report to the Land Use Inspector at (867) 777-2090, indicating the quantity of material quarried and the quantity of material removed from the site. Failure to submit the monthly report within the indicated time frame may result in cancellation of this permit as per section 9(6) of the regulations.

13. Upon expiry of the permit, the Permittee must submit a Final Plan to the Land Use Inspector for reconciliation and approval. Failure to submit a Final Plan within 60 days of project completion may result in rejection of future Quarry Permit Applications until rectified.

14. A permittee who over-quarries may be ineligible for future quarry permits for a twelve month period and additional legal action may be taken by the Land Use Inspector under the Territorial Quarrying Regulations.

15. This permit is subject to the provisions of the Territorial Quarrying Regulations and the conditions set out herein. Failure to comply with the provisions of the Regulations and the



ENVIRONMENTAL INSPECTION REPORT

conditions prescribed in this permit may result in cancellation of the permit in accordance with Section 9(6) of the Territorial Quarrying Regulations without prior notice to the Permittee.

Please ensure that these items are action on to avoid any future rejection of quarry permits.

MATTERS FOR FOLLOW UP

Permittee is to provide volumes taken from source 251 as per QP conditions.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3

