



Telephone: 867 777-8900

Fax: 867-777-2090

February 15, 2021

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

Attention: **Bob Gully**

**File Number** G16Q004  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 251

To: **Bob Gully,**

An inspection of the above noted operation was conducted on February 15, 2021 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region  
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



### ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF February 01, 2021

Continued removal of stock piles are to be done.

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	February 01, 2021
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 15, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	on going		
<b>Program Modifications Approved:</b>	nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	<b>Km 251</b>			
Location as Permitted	U			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

**Km 251:**

During this inspection it was observed that stock piles previously requested for removal was done except that a small pile still remains in front of another permit holders work location, this is to be removed prior to any further activities under your existing quarry permit.

Further, it was previously mentioned on previous inspection reports that no stock piles or storage is to be done in the central location of the pit and in particular in other permit holders work areas as this is a multi-user pit/source.

It was observed that equipment is being parked at the entrance area of the floor and as well in front of another permit holders work area, again this is to be corrected immediately prior



### ENVIRONMENTAL INSPECTION REPORT

to any further work at this site.

Although a blast occurred and the pre data was provided for that location it was observed that drilling is in progress for another blast, this was indicated by bob that this was going to occur, however it was further stated in last inspection report dated February 01, 2021 that any new locations a pre blast must be submitted.

Please note that no blasting shall occur until the Department of Lands is in receipt of the pre-data for this blast.

Current equipment by entrance shall be moved and the small stock pile is to be removed prior to any further work being done at the pit.

#### MATTERS FOR FOLLOW UP

Current equipment by entrance shall be moved and the small stock pile is to be removed prior to any further work being done at the pit.

*N/A*

Representative Signature

Inspector's Signature




# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

**equipment by entrance as well small stock pile to be removed.**



**Figure 2**

**equipment by entrance**







## ENVIRONMENTAL INSPECTION REPORT

**Figure 3**  
equipment by entrance



**Figure 4**  
drilling in progress

