



Telephone: 867 777-8900  
Fax: 867-777-2090

February 22, 2018

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

Attention: Lyle Gully

File Number G16Q004  
Type of Operation QUARRY SITE - Existing  
Location Km 251

To Lyle Gully,

An inspection of the above noted operation was conducted on February 20, 2018 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region  
GLWB



### ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF January 30, 2018  
 Payments to be received for the overages for 2018QP0001 and that material are continually being removed.

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	January 30, 2018
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 20, 2018
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	Ongoing		
<b>Program Modifications Approved:</b>	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	<b>Km 251</b>				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Matters not Inconsistent	U				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Facilities	A				
Chemicals	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				
Location as Permitted	A				

**Explanatory Remarks -**  
**Km 251:**  
 During the last inspection dated January 31, 2018 proponent was informed that material was to be continually removed from site and that the overages of 1788 cm. be paid.  
 Please note that neither observations have yet to be done it is again recommended that the overages be dealt with A.S.A.P. failure to correct the overages may result in further actions condition 14 of your Quarry Permit which states the following:  
 "A permittee who over-quarries may be ineligible for future quarry permits for a 12 month period and legal action may be taken by the Land Use Inspector under the Territorial Quarrying Regulations."  
 The second recommendations informed was that material was to be continually removed from site as this is a multi-user site and with material not being removed will restrict access for other users and may become a safety concern.  
 It is again recommended that the overages of 1788 cm be dealt with and that material

<b>Date:</b>	February 20, 2018	<b>Permit #:</b>	G16Q004	<b>Page No:</b>	1
--------------	-------------------	------------------	---------	-----------------	---



### ENVIRONMENTAL INSPECTION REPORT

previously quarried be removed from site.

**MATTERS FOR FOLLOW UP**

Ensure Payments for overages of 1788 (cm) are made, and material is to be continually removed.

Representative Signature

Inspector's Signature

Date:	February 20, 2018	Permit #:	G16Q004	Page No:	2
-------	-------------------	-----------	---------	----------	---

# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**



Date:	February 20, 2018	Permit #:	G16Q004	Page No:	3
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	February 20, 2018	Permit #:	G16Q004	Page No:	4
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6



Date:	February 20, 2018	Permit #:	G16Q004	Page No:	5
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8



Date:	February 20, 2018	Permit #:	G16Q004	Page No:	6
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Figure 9



Date:	February 20, 2018	Permit #:	G16Q004	Page No:	7
-------	-------------------	-----------	---------	----------	---