

## Permits

---

**From:** Miki Ehrlich <mehrllich@mvlwb.com>  
**Sent:** Tuesday, September 03, 2013 11:45 AM  
**To:** 'Permits'  
**Subject:** FW: Lease Inspection Reports 75M14-1 and 76D2-1

Please post to MV2013J0006 – Reports and studies – Inspection reports

Title: TNS response to inspection report – Aug31-13

---

**From:** Gary Jaeb [mailto:gary@truenorthsafaris.com]  
**Sent:** Saturday, August 31, 2013 9:26 PM  
**To:** Nahum Lee  
**Cc:** Clint Ambrose; Scott Stewart; Shelley Hauck  
**Subject:** Re: Lease Inspection Reports 75M14-1 and 76D2-1

Nahum et al

I have just returned from Mackay lake lodge and we have completed work on some of the items noted in your 2012 inspection report. As you know we were not at the lodge when you conducted the 2012 inspection and we did not receive your report until after the fall season was over and the ground was frozen.

I discussed this with you or Clint at that time and understood that we would have this season, 2013 to do our work and the next inspection would be in 2014. However, I note now that you did another inspection this summer and again we were not at the lodge and had not done any of the required work from your 2012 report.

We have not operated full time in recent years so it is necessary to call me to coordinate times when we will be there.

Also, our ability to repair and replace buildings and equipment is limited by the economic times and we trust that you can bear with us.

Archie Doctor and Ricky Drygeese worked with me this past week at the Lodge and we have some digital photos of the work that we completed. We could arrange a date to meet with you and go over our plans and your expectations.

We did repair our recycling storage tent frame with a new cover and door. The second building that you identified in the 2012 report as not being clad to weather, has been used in the past as a taxidermy workshop. As you know, we have not used that buildings since the caribou hunting closure in 2009. The tarps that cover the structures have been damaged by the wind and while we do have replacement tarps at the site, we have decided not to put them on until the buildings will be used again, as the tarp will simply become weathered again with no useful purpose.

The staff house that had the roofing tarp blown off last winter was identified in your 2013 report. We have removed the damaged roofing material and have placed the contents in another building until we need the staff house again and can make the necessary repairs.

We have completed excavations of the stained ground material at the 1/2 way cabin and the generator building.

We did not complete the replacement of the stained material near our tractors and equipment. I do want to clarify that our equipment is not leaky, rather some minor spills were the result of maintenance work by a mechanic who no longer works with us. We did get the equipment moved last week, so that the necessary clean up can be completed next summer.

We removed the barrels from the lake where the old dock was, as we have decided not to replace it at this time.

We removed 15 empty fuel drums on an empty back haul last week, and will try again to access some of the remaining ones next winter or on empty back haul flights. We were not able to get to the lodge last winter for a number of reasons including timing, a late season storm and lack of money.

We have sorted old batteries for winter trucking back to Yellowknife. We have not reorganized our spare parts/junk pile but will as we have time.

We noted that someone has forcefully removed the door from our incinerator and we will attempt repairing it next summer. The door was attached with heavy welded hinges that are twisted and broken.???

We are applying to AANDC to amend our lease to allow us to continue to bury ashes and non toxic waist and will welcome your advise and assistance/inspection standards. In the past we were told that all ashes/waist had to have 1 meter of cover so as to avoid exposure over time.

Mahsi  
Gary Jaeb

**From:** [Nahum Lee](#)  
**Sent:** Monday, August 26, 2013 4:29 PM  
**To:** [Gary Jaeb](#)  
**Cc:** [Clint Ambrose](#) ; [Scott Stewart](#) ; [Shelley Hauck](#)  
**Subject:** Lease Inspection Reports 75M14-1 and 76D2-1

Hello Gary,

Please find attached, the latest environmental inspection reports for the above noted leases. The original reports will follow by mail. If there are any questions or concerns, please contact Clint Ambrose at 867.669.2794 or myself at the numbers below. Take care and have a good day.

Regards,

Nahum

Nahum D. Lee  
Resource Management Officer II  
Aboriginal Affairs and Northern Development Canada  
South Mackenzie District

140 Bristol Ave. (Street)  
#16 Yellowknife Airport (Mailing)  
Yellowknife, NT.  
X1A 3T2  
Cell: (867)444-8491  
Phone: (867) 669-2757  
Fax: (867) 669-2720  
email: [nahum.lee@aandc.gc.ca](mailto:nahum.lee@aandc.gc.ca)