

From: [Julian Morse](#)
To: [Permits](#)
Subject: FW: Bullmoose-Ruth Remediation Project - Winter Road Update
Date: Friday, November 25, 2016 10:23:47 AM

Please post to MV2016X0013 and MV2016L8-0004 in consultations-reviews

From: Ron Breadmore [mailto:Ron.Breadmore@aandc-aadnc.gc.ca]
Sent: Thursday, November 24, 2016 5:45 AM
To: Julian Morse <jmorse@mvlwb.com>
Cc: Carey Ogilvie <Carey.Ogilvie@aandc-aadnc.gc.ca>
Subject: Fwd: Bullmoose-Ruth Remediation Project - Winter Road Update

Hi Julian,

Here's our followup to Ken Yoder at Hearne Lake Lodge re: 500m buffer. I will check in with you next week and see how things are looking leading up to the Board's December 5th meeting.

Ron

Ron Breadmore

BASc (Env. Health), CPHI(C), PMP
Project Manager and EHS Team Lead
Contaminants & Remediation Division -
Indigenous & Northern Affairs Canada
Box 1500, Yellowknife, NT X1A 2R3
ph: (867) 669-2743 cell. (867) 446-1193
Ron.Breadmore@aandc-aadnc.gc.ca

Note: The information contained in this E-mail is private and confidential information intended only for the use of the addressee(s). If you are not the intended recipient, or an agent responsible for delivering the message to the intended recipient, you are hereby notified that any disclosure or distribution of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by telephone. Thank-you.

>>> Ron Breadmore 11/23/2016 3:44 PM >>>

Hello Ken,

Further to your comments to the MVLWB during their recent draft permit review process regarding a 500m buffer between the BMR winter road and your lodge (and INAC-CARD's subsequent response), I wanted to provide you with an update in this regard.

Through discussions with our Project Management Team and the Remediation Contractor/winter road builder, Rowe's-Outcome Joint Venture, it has been determined that a 500m buffer is achievable. The Contractor completed a track survey through the channel in September and reports that the section of the historic route in question (shown on one of the update maps as running along the shoreline directly below your lodge) can be readily pushed 500m to the north. All reasonable efforts will be made to maintain the 500m buffer. In the event that route modifications are required due to ice conditions and safety considerations, the changes will be minimized to extent possible and INAC will notify you promptly.

If you have any questions or concerns regarding this, please don't hesitate to give me a call.

best regards,

Ron

Ron Breadmore

BASc (Env. Health), CPHI(C), PMP

Project Manager and EHS Team Lead
Contaminants & Remediation Division -
Indigenous & Northern Affairs Canada
Box 1500, Yellowknife, NT X1A 2R3
ph: (867) 669-2743 cell. (867) 446-1193
Ron.Breadmore@aandc-aadnc.gc.ca

Note: The information contained in this E-mail is private and confidential information intended only for the use of the addressee(s). If you are not the intended recipient, or an agent responsible for delivering the message to the intended recipient, you are hereby notified that any disclosure or distribution of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately by telephone. Thank-you.