



Telephone: 1-867-587-7205

Fax: 1-867-587-2928

September 29, 2020

Husky Oil Operations Limited
707 - 8th Avenue, S.W.
Box 6525 Station D
Calgary, AB T2P 3G7

Attention: Dean Clemenson

File Number	S04A-006
Type of Operation	OIL AND GAS DRILLING - WELLSITE
Location	L-71 Wellsite

Dear Dean Clemenson

An inspection of the above-noted operation was conducted on September 1, 2020, by Manager, Resource Management Jonathan Gillingham.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me by phone at 1-867-587-7205 or by email at Jonathan_Gillingham@gov.nt.ca.

Sincerely,

Jonathan Gillingham
Manager of Resource Management
Department of Lands
Sahtu Region

CC: Sathu Land and Water Board
Trevor Bremner – Regional Superintendent, Sahtu Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Husky Oil Operations Limited	Permit Expiry Date:	September 11, 2009
Land Use Permit No.	S04A-006	Previous Inspection:	July 10, 2019
Quarrying Permit No.	N/A	Inspection Date:	September 01, 2020
Contractor:	N/A	Subcontractor:	N/A
Location(s) Inspected:	L-71 Wellsite		
Current Stage of Operation:	Remediation		
Program Modifications Approved:	None		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	L-71				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	N/A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	N/A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	N/A				
Historical / Archaeological Sites	N/A				
Ecological Resources	A				
Fuel Storage	N/A				
Brush Disposal	N/A				
Restoration of Lands	A				
Permits	N/A				
Matters not Inconsistent	N/A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

L-71:

There have been no significant changes since the last Inspection Report (July 16, 2019). Inspector still requires to keep this file open to monitor vegetation growth. As stated in the previous Inspection Report, there are still areas with sparse vegetation growth. Inspector is not confident in the complete success of the remediation with this wellsite. Inspector will continue to monitor and update accordingly.

N/A

Representative Signature



Inspector's Signature

Date:	September 01, 2020	Permit #:	S04A-006	Page No:	1
-------	--------------------	-----------	----------	----------	---




ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Wellpad L-71



Date:	September 01, 2020	Permit #:	S04A-006	Page No:	2
-------	--------------------	-----------	----------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 2

Well center of L-71





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Aerial of wellpad L-71



Figure 4

Aerial of wellpad L-71

