



Aboriginal Affairs and  
Northern Development Canada

Affaires autochtones et  
Développement du Nord Canada

<http://www.aandc-aadnc.gc.ca>

<http://www.aadnc-aandc.gc.ca>

North Mackenzie District  
P.O. Box 2100  
Inuvik, NT, X0E 0T0

Telephone: 867-777-8900  
Fax: 867-777-2090

February 18, 2013

Husky Oil Operations Ltd.  
707-8th Avenue SW  
Calgary, AB T2P 3G7

**Attn: Kim Richardson**

**RE: Land Use Permit S12X-006  
MISC.  
Miscellaneous - Groundwater Monitoring Program**

Dear Kim Richardson,

An inspection of the above noted operation was conducted on February 12, 2013 by Resource Management Officer Jozef Carnogursky.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8900.

Sincerely,



Conrad Baetz  
District Manager

Cc: Sahtu Land and Water Board  
RMO- Norman Wells



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Husky Oil Operations Ltd.	<b>Permit Expiry Date:</b>	December 04, 2017
<b>Land Use Permit No.</b>	S12X-006	<b>Previous Inspection:</b>	January 09, 2013
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	February 12, 2013
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Miscellaneous - Groundwater Monitoring Program		
<b>Current Stage of Operation:</b>	Active		
<b>Program Modifications Approved:</b>			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	<b>Clearings</b>			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	U			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	N/I			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	N/I			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

Clearings:

The ground beneath the holding tank at one of the water source wells was showing signs of melting due to the steam and hot liquids.

Holding tanks associated with water source monitoring should be placed on rig mats to reduce the chances of the ground from melting and rutting.

\_\_\_\_\_  
Representative Signature

  
Inspector's Signature