



Indian and Northern
Affairs Canada
www.inac.gc.ca

Affaires Indiennes
et du Nord Canada
www.ainc.gc.ca

North Mackenzie District
P.O. Box 2100
Inuvik, NT XOE 0T0

Telephone: (867) 777-3361
Fax: (867) 777-2090

November 10, 2008

Cyries
C/O Iterations
700-700 2nd Avenue, S.W.
CALGARY, AB T2P 2W1

RECEIVED
NOV 13 2008

Attn: Kyla Cuthbertson

Re: Land Use Permit G02A014
Drilling Program, Tree River B-10

To Ms. Cuthbertson,

On June 30, 2008 Resource Management Officer Don Arey, conducted an inspection of your operation under the above mentioned Land Use Permit.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report.

Attached are also the requirements for a Final Plan, should you have no further activities at this site, you may submit your final plan to this office for review to proceed in the process of file closure.

If you have any questions, please contact our office at (867) 777-3361.

Regards,

Don Arey
Resource Management Officer

Cc: Conrad Baetz, District Manager, North Mackenzie District, Inuvik, NT
Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Cyries C/O Iterations 700-700 2 nd S.W. CALGARY, AB T2P 2W1		
	Permit Expiry Date	Last Previous Inspection	
Land Use Permit No.	G02A014	December 31 st , 2005	July 4 th , 2005
Quarrying Permit No.			
Contractor:	Canadian Petroleum Eng.	Subcontractor:	

Location(s) Inspected:	Tree River – B10
------------------------	------------------

Current Stage of Operation:	
-----------------------------	--

Program Modifications Approved:	NIL
---------------------------------	-----

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

	Operating Condition	Aspect Inspected		
		Well post		
A	Location as Permitted	A		
B	Timing as Permitted	A		
C	Equipment as Approved	A		
D	Methods & Techniques	A		
E	Facilities	A		
F	Erosion	A		
G	Chemicals, Waste	A		
H	Wildlife and Fisheries Habitat	A		
I	Ecological Resource	---		
K	Fuel Storage	A		
L	Brush Disposal	N/A		
M	Matters Not Inconsistent	A		
N	Water Engineering	N/A		
O	Water Supply	N/A		
P	Restoration	N/A		
Q	Quarrying Methods	N/A		
R	Sections 12 to 19 T.L.U.R.	A		
S				
T				

Explanatory Remarks (attach page 2 if required)	
(see page 2)	

N/A
Representative Signature


Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT Pg. 2
(Continued)

Date:	June 30, 2008	Permit #:	G02A0014
-------	---------------	-----------	----------

General Comments: (Continued)

All aspects of the program looked satisfactory at time of inspection. Recommend file for closure

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT Pg. 3 (Continued)

Date:	June 30, 2008	Permit #:	G02A014
-------	---------------	-----------	---------

Inspection Images

Figure 1:



Figure 2:



Figure 3:



Figure 4:



Figure 5:



Figure 6:





Gwich'in Land and Water Board

Box 2018 Inuvik NT X0E 0T0

PH 867 777 7860 FX 867 777 7870

October 16, 2008

File: G02A011
G02A012
G02A013
G02A014

Indian and Northern Affairs Canada
North Mackenzie District
Attn: Conrad Baetz
P.O. Box 2100
Inuvik, NT X0E 0T0

Re: Status – required monitoring and remediation activities, land use permit numbers
G02A011, G02A012, G02A013, G02A014 Cyries Energy Inc.

Conrad,

The latest correspondence on our files is a letter by Cyries Energy Inc. to Indian and Northern Affairs Canada (INAC), dated June 29, 2007. This letter was in response to a request by INAC, issued January 2007, directing the permittee to address outstanding issues at various locations covered by the above land use permits.

Could you please provide us with an update on these files. We are interested to find out if the permittee has complied with the recommended action, and what the outcomes of the monitoring and remediation activities are.

Please let me know if you have any questions or require clarification.

Sincerely,

Helga Harlander
Land and Water Technician