



Telephone: 867-777-8907
Fax: 867-777-2090

September 13, 2021

L.J.'s Septic Services & Contracting Ltd.
P.O. Box 151
Fort McPherson, NT X0E 0J0

Attention: Leslie J Blake

File Number G16Q001
Type of Operation QUARRY SITE - Existing
Location Frog Creek

Dear Leslie J Blake,

An inspection of the above noted operation was conducted on September 09, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB
GTC

Bag Service 1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

Permittee:	L.J.'s Septic Services & Contracting Ltd.	Permit Expiry Date:	March 14, 2021
Land Use Permit No.	G16Q001	Previous Inspection:	April 22, 2021
Quarrying Permit No.		Inspection Date:	September 09, 2021
Contractor:	L.J.'s Septic Services & Contracting Ltd.	Subcontractor:	
Location(s) Inspected:	Frog Creek		
Current Stage of Operation:	On going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Frog Creek				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				

Explanatory Remarks -

Frog Creek:

During the inspection on September 9, 2021 at the Frog Creek quarry site there was a few concerns with oil spills under three of the equipment.

There is an oil spill under the Volvo loader, the cat loader and under the excavator and also a few small spills near the 3054 crusher that should be cleaned up. There is also a spill tray that has some unknown liquid chemical in the tray at the site.

The rest of the site looks clean and in good order.

Representative Signature

Inspector's Signature

Date:	September 09, 2021	Permit #:	G16Q001	Page No:	1
-------	--------------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

