



Telephone: 867 777-8900

Fax: 867-777-2090

April 8, 2021

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

**Attention: Bob Gully**

**File Number** G16Q004  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 251

To: Bob Gully,

An inspection of the above noted operation was conducted on April 08, 2021 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey  
Manager, Resource Management  
Department of Lands  
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region  
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	March 15, 2021
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	April 08, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	on going		
<b>Program Modifications Approved:</b>	nil		

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Fuel Storage	A			
Brush Disposal	N/A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

**Explanatory Remarks -**

**Km 251:**

During the inspection it was observed that crushing is in the process and material is piled on the southerly side of the pit floor. It was also observed that one end dump truck was burned, no indication of any spills observed as result. Please note that should there not be any legal requirement for the vehicle to be there, please ensure that the burned vehicle is removed and area cleaned up.

Just as a reminder that your permits expire on May 25 2021, and has temporary stock piling of which is to be removed from site, please ensure that these are complied with.



## ENVIRONMENTAL INSPECTION REPORT

### MATTERS FOR FOLLOW UP

as a reminder that your permits has temporary stock piling of which is to be removed from site, please ensure that these are complied with.

*N/A*

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:  
**Figure 1**



**Figure 2**








# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6








# ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8







# ENVIRONMENTAL INSPECTION REPORT

Figure 9



Figure 10







# ENVIRONMENTAL INSPECTION REPORT

Figure 11

