



Telephone: 867 777-8900

Fax: 867-777-2090

April 29, 2021

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Bob Gully

File Number	G16Q004
Type of Operation	QUARRY SITE - Existing
Location	Km 251

To Bob Gully,

An inspection of the above noted operation was conducted on April 29, 2021 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to noted conditions in the general comments section of this report. Your attention to this matter is appreciated.


If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT X0E 0T0





ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF April 08, 2021

as a reminder that your permits has temporary stock piling of which is to be removed from site, please ensure that these are complied with.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	April 08, 2021
Quarrying Permit No.		Inspection Date:	April 29, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	on going		
Program Modifications Approved:	nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted	A			
Time as Permitted	A			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Km 251:

Bob Gully called inspector requesting that he would like to blast another location inspector had gone out to meet with Bob at Km 251 wher it was observed that material was being removed and other permittees work area are being cleared off. Bob was informed that his current permit is for 5000cm, he informed at the moment that he is unsure what was blasted and informed might be under the permitted amount. Bob was further informed that the post data is required and that the area be cleared to get the post data of which he informed will be done and may take a couple days to clear but will be done. Bob informed of the



ENVIRONMENTAL INSPECTION REPORT

location that he required to get more material from as their estimated amount might be lower than anticipated, he was then advised as the new location was from a previous blast portion of that post data can be used for the pre data of which he will discuss with the surveyor. Bob was then informed that as it is uncertain on the volumes at the moment these data are to be provided and should volumes be over the permitted amount he informed they will get dealt with right away, Inspector was in agreement with the discussion and outcome of what may occur.

Aside from this all matters was satisfactory to inspector.

MATTERS FOR FOLLOW UP

as a reminder that your permits has temporary stock piling of which is to be removed from site, please ensure that these are complied with. Also that Please ensure that the post data is provided to determine volumes quarried.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3




Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

