



Telephone: 867 777-8900
Fax: 867-777-2090

February 1, 2021

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Bob Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

To: Bob Gully,

An inspection of the above noted operation was conducted on February 01, 2021 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF January 19, 2021

Materials to the North side wall are to be removed.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	January 19, 2021
Quarrying Permit No.		Inspection Date:	February 01, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	on-going		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -
 Km 251:
 During the inspection it was observed that requested stock piles at the northern side of pit is currently being removed. The pre survey of the blast was provided on June 16 2020, please ensure that the post data for this location is provided, once this area is completed. Further any new location a pre blast must be provided prior to blasting. Please ensure that all terms and conditions of your permits are adhered to.

MATTERS FOR FOLLOW UP

Continued removal of stock piles are to be done.

 Representative Signature

 Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

