



Telephone: 867 777-8900

Fax: 867-777-2090

June 24, 2021

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Bob Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

To: Bob Gully,

An inspection of the above noted operation was conducted on June 23, 2021 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent Lands, Beaufort Delta Region
GLWB

Bag Service #1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF June 10, 2021

As a reminder our office requires all pre and post data for any blasts that occurred. Further equipment are not to be parked in other permit holders work location. Please note as well stock piles are to be continually removed from site, as per your L.U.P. Part A scope of Permit, item 1 a . temporary stockpiling and hauling of granular material from the quarry at km 251, also the central area of the pit is to be free of any stock piles and equipment.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	June 10, 2021
Quarrying Permit No.		Inspection Date:	June 23, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	on going		
Program Modifications Approved:	LUP extended to May25, 2023		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Km 251			
Location as Permitted				
Time as Permitted				
Equipment as Approved (Type & Size)				
Methods & Techniques				
Facilities				
Erosion (Control or Prevention)				
Chemicals				
Wildlife and Fisheries Habitat (Protection)				
Wastes				
Historical / Archaeological Sites				
Ecological Resources				
Fuel Storage				
Brush Disposal				
Restoration of Lands				
Permits				
Matters not Inconsistent				
Sections 8 to 12 / 14 to 16				
M.V.L.U.R.				

Explanatory Remarks -

Km 251:

During this inspection it was observed that one gravel truck was removing material from the site and no other work being done at time of inspection. No obstructions was observed in other permit holders work locations.

Date:	June 23, 2021	Permit #:	G16Q004	Page No:	1
--------------	---------------	------------------	---------	-----------------	---



ENVIRONMENTAL INSPECTION REPORT

As per previous inspection report dated June 01, 2021 it was mentioned in the report that pre and post data for the May 19th, 2021 blast was required.

Your current volume remaining on your QP is 1497cm

MATTERS FOR FOLLOW UP

As a reminder our office requires all pre and post data for any blasts that occurred. We are currently awaiting the May 19, 2021 blast data. Further equipment are not to be parked in other permit holders work location. Please note as well stock piles are to be continually removed from site, as per your L.U.P. Part A scope of Permit, item 1 a . temporary stockpiling and hauling of granular material from the quarry at km 251, also the central area of the pit is to be free of any stock piles and equipment.

N/A

Representative Signature

Inspector's Signature

Date:	June 23, 2021	Permit #:	G16Q004	Page No:	2
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4



Date:	June 23, 2021	Permit #:	G16Q004	Page No:	4
-------	---------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Figure 5



Date:	June 23, 2021	Permit #:	G16Q004	Page No:	5
-------	---------------	-----------	---------	----------	---