

RECEIVED  
Nov 15 10 2021

Government of Northwest Territories  
Gouvernement des Territoires du Nord-Ouest

Telephone: 867-777-8907  
Fax: 867-777-2090

November 4, 2021

Bob's Welding Ltd.  
P.O. Box 2644  
Inuvik, NT X0E 0T0

**Attention: Bob Gully**

**File Number** G16Q004  
**Type of Operation** QUARRY SITE - Existing  
**Location** Km 251

Dear Bob Gully,

An inspection of the above noted operation was conducted on November 03, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,



Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB

Bag Service 1, Inuvik, NT X0E 0T0



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Bob's Welding Ltd.	<b>Permit Expiry Date:</b>	May 25, 2021
<b>Land Use Permit No.</b>	G16Q004	<b>Previous Inspection:</b>	September 16, 2021
<b>Quarrying Permit No.</b>		<b>Inspection Date:</b>	November 03, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 251		
<b>Current Stage of Operation:</b>	on-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>Km 251</b>				
Location as Permitted	A				
Time as Permitted	U				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	U				
Matters not Inconsistent	U				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks - Km 251:**

During the inspection on November 3, 2021 at Km 251 gravel source there were a couple of concerns observed by the inspector.

There are numerous stock piles of material on the pit floor which makes it unsafe for workers and other users to manoeuvre safely at the site.

It was mentioned in previous inspection reports that no stock piles or storage is to be conducted in the central location of the pit and in particular in other permit holders work areas as this is a multi-user pit/source. There is material being removed from the site at this time but at a slow rate.

A recent survey from Coreman Technical Services shows that total volumes taken at Km 251 from Feb 17, 2021 to Oct. 31<sup>st</sup>, 2021 is for a total amount of 12,165cm removed from Km 251 this gives an average of 7165cm.

**MATTERS FOR FOLLOW UP**

Please ensure that the overages are paid and note that no new quarry permits may be issued until the Department of Lands has been informed that overages have been paid and material removed from the central area of the pit floor.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature


Date:	November 03, 2021	Permit #:	G16Q004	Page No:	1
-------	-------------------	-----------	---------	----------	---



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





# ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6

