



Telephone: 867 777-8900
Fax: 867-777-2090

March 3, 2022

Department of Infrastructure
3rd Flor, Tatsaotine Building 5015-49st
Yellowknife, NT X1A 2L9

Attention: Terry Brookes

File Number G18X005
Type of Operation MISC.
Location wind tower access

To: Terry Brookes,

An inspection of the above noted operation was conducted on March 02, 2022 by Manager, Resource Management Donald Arey.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: Dan Carmichael, Regional Superintendent, Beaufort Delta Region

GLWB

Bag Service #1, Inuvik, NT X0E 0T0



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF February 09, 2022

Ensure Term and Conditions are followed

Permittee:	Department of Infrastructure	Permit Expiry Date:	November 26, 2025
Land Use Permit No.	G18X005	Previous Inspection:	February 09, 2022
Quarrying Permit No.	2021QP0032	Inspection Date:	March 02, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	wind tower access		
Current Stage of Operation:	just in mulching stage on access road.		
Program Modifications Approved:	nil		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	KM 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Ecological Resources	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

KM 251:

During the inspection it was observed that tracked vehicles are using the access at the start off the Dempster Highway. Also observed that logs are being piled on south portion of access start of road. Inspector had spoken with Robert Cole with J.B. Firth contracting and he informed that they are only mulching at the moment and have one skid steer and a D3 a couple kms up the access mulching, and they are staying with the 40 meter R.O.W.

No concerns observed during this time of inspection. A ski-doo patrol will be made at a later dater to confirm all activity are within the access road.



ENVIRONMENTAL INSPECTION REPORT

As for the quarry permit at Km 251 it was observed that no activity is going on at the quarry site.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2

Start of access





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4
flagging for drill holes

