



Telephone: 867-777-8907
Fax: 867-777-2090

July 15, 2021

Bob's Welding Ltd.
P.O. Box 2644
Inuvik, NT X0E 0T0

Attention: Bob Gully

File Number G16Q004
Type of Operation QUARRY SITE - Existing
Location Km 251

Dear Bob Gully,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen
Resource Management Officer II
Department of Lands
Beaufort Delta Region

CC:
Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region
GLWB



ENVIRONMENTAL INSPECTION REPORT

FOLLOW UP MATTERS FROM PREVIOUS INSPECTION OF June 23, 2021

Please note as well stock piles are to be continually removed from site, as per your L.U.P. Part A scope of Permit, item 1 a . temporary stockpiling and hauling of granular material from the quarry at km 251, also the central area of the pit is to be free of any stock piles and equipment.

Permittee:	Bob's Welding Ltd.	Permit Expiry Date:	May 25, 2021
Land Use Permit No.	G16Q004	Previous Inspection:	June 23, 2021
Quarrying Permit No.		Inspection Date:	July 13, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	U				
Wastes	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

Km 251:

During the inspection on July 13, 2021 at Km 251 gravel source there is a couple of concerns observed by the inspector.

During the time of the inspection there was no work occurring at the time of the inspection. There are a few spills on the pit floor in various places that needs to be cleaned up and the stock piles of gravel are building up with in the pit floor and along the pit walls that needs be removed from the site.

Please note as well stock piles are to be continually removed from site, as per your L.U.P. Part A scope of Permit, item 1 a . temporary stockpiling and hauling of granular material from the quarry at km 251, also the central area of the pit is to be free of any stock piles and equipment.

The rest of the site looks in good order.

Representative Signature

Inspector's Signature

Date:	July 13, 2021	Permit #:	G16Q004	Page No:	1
--------------	---------------	------------------	---------	-----------------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

