



Telephone: 867-678-8090 ext. 24653
Fax: 867-777-2090

May 14, 2024

Northwind Industries Ltd.
P.O. Box 1130
Inuvik, NT X0E0T0

Attention: Fred Bailey

File Number G19Q009
Type of Operation QUARRY SITE - Existing
Location Km 251

Dear Fred Bailey,

An inspection of the above noted operation was conducted on May 09, 2024 by Resource Management Officer Herbert Allen and Resource Management Officer Bradley Voudrach.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24653.


Sincerely,

Herbert Allen
Resource Management Officer
Environment and Climate Change,
Department of Land and Water
Beaufort Delta Region

CC:

Donald Arey, Regional Superintendent, Department of Environment and Climate Change Land and Water, Beaufort Delta Region
GLWB

Bag Service 1, Inuvik, NT X0E 0T0





ENVIRONMENTAL INSPECTION REPORT

Permittee:	Northwind Industries Ltd.	Permit Expiry Date:	December 02, 2024
Land Use Permit No.	G19Q009	Previous Inspection:	April 23, 2024
Quarrying Permit No.	2024QP0006	Inspection Date:	May 09, 2024
Contractor:	Northwind	Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	On-going		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Km 251				
Location as Permitted	A				
Time as Permitted	U				
Equipment as Approved (Type & Size)	U				
Methods & Techniques	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wastes	A				

Explanatory Remarks - Km 251:

During the inspection at Km 251 quarry on May 9, 2024 and May 13, 2024 there were a couple of concerns observed by the inspector.

There is a large stockpile of material near the right of way to the highway that looks to be about 30,000 to 40, 000 cubic meters. It appears that Northwind is over the limit of the quarry permit and Northwind will have to apply for a new quarry permit or pay for overages. There is a lot of material that did go to Tuk work site and also being stockpile at another site in the community.

During a site inspection on May 13, 2024 there was no work being conducted at the back of the quarry where they were drilling, blast, clearing and excavating. The work that was being conducted was with the stockpile at the south east side of the quarry. The rock truck that is broken in half is still at the site and needs to be removed.

At this time ECC Lands require the post data and the quarry returns to be updated to show what was extracted from the pit. ECC Lands also require a plan for the material that is stockpiled at the southeast corner of the quarry. There will be a time period set for the stockpile to be removed from the site.

Bob's welding will be starting their work at the Km 251 pit within a week or so and they will require a work area to start their work. ECC Lands and Bob's will be going to the quarry site to pick out a work area so they have an assigned work area.

Representative Signature

Inspector's Signature

Date:	May 09, 2024	Permit #:	G19Q009	Page No:	1
-------	--------------	-----------	---------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:
Figure 1



Figure 2





ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4





ENVIRONMENTAL INSPECTION REPORT

Figure 5



Figure 6





ENVIRONMENTAL INSPECTION REPORT

Figure 7



Figure 8

