



Telephone: 867-678-8090 ext. 24656

Fax: 867-777-2090

May 23, 2023

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location KM 235 (Follow-up inspection from 2022 season)

Dear Mosiul Alam,

I conducted an inspection of the above noted operation on May 19, 2023. This was a follow up inspection for issues identified during my last inspection report dated October 18, 2022.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-678-8090 ext. 24656 .

Sincerely,

Jozef Carnogursky
Resource Management Officer
Department of Environment and
Climate Change
Inuvik, NT

CC: Gwich'in Land and Water Board



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	October 18, 2022
Quarrying Permit No.		Inspection Date:	May 19, 2023
Contractor:	LJ's Contracting	Subcontractor:	
Location(s) Inspected:	KM 235 (Follow-up inspection from 2022 season)		
Current Stage of Operation:	Inactive		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Operation				
Time as Permitted	N/I				
Equipment as Approved (Type & Size)	N/I				
Methods & Techniques	N/I				
Facilities	U				
Erosion (Control or Prevention)	N/I				
Chemicals	N/I				
Wildlife and Fisheries Habitat (Protection)	N/I				
Wastes	U				
Historical / Archaeological Sites	N/I				
Ecological Resources	N/I				
Fuel Storage	N/I				
Brush Disposal	N/I				
Restoration of Lands	U				
Permits	N/I				
Matters not Inconsistent	N/I				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	N/I				
Location as Permitted	N/I				

Explanatory Remarks -

Operation :

A follow up inspection from issues arising from an inspection done on October 18, 2022 at KM 235 found that clean up of the location did not occur. This site had a temporary camp situated on this site for Infrastructure projects in 2022 and debris and garbage was left on site and has yet to be cleaned up and disposed of to a proper facility.

It is highly recommended that the debris and garbage previously identified to the permit holder, be cleaned and hauled to a proper facility for disposal. Possible legislative actions may be considered by the Department of Environment and Climate Change if this is not rectified as soon as possible.



ENVIRONMENTAL INSPECTION REPORT

--

Representative Signature

[Handwritten Signature]

Inspector's Signature

Inspection Images:

Figure 1

Figure 2

