



Telephone: 867 777-8900

Fax: 867-777-2090

June 14, 2022

Department of Infrastructure
Bag service # 1
106 Veteran Way
Inuvik, NT X0E0T0

Attention: Mosiul Alam

File Number G21E001
Type of Operation HWY MAINTENANCE & OPERATIONS
Location Km 251

To: Mosiul Alam,

An inspection of the above noted operation was conducted on June 13, 2022 by Manager, Resource Management Donald Arey and Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.


If you have any questions, please contact me at 867 777-8900.

Regards,

Donald Arey
Manager, Resource Management
Department of Lands
Beaufort Delta Region

CC: GLWB

Bag Service #1, Inuvik, NT X0E 0T0





ENVIRONMENTAL INSPECTION REPORT

Permittee:	Department of Infrastructure	Permit Expiry Date:	June 27, 2026
Land Use Permit No.	G21E001	Previous Inspection:	May 18, 2022
Quarrying Permit No.		Inspection Date:	June 13, 2022
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 251		
Current Stage of Operation:	QP 2022QP0001 O&M		
Program Modifications Approved:	NIL		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Operation			
Location as Permitted	U			
Time as Permitted	U			
Equipment as Approved (Type & Size)	A			
Methods & Techniques	A			
Facilities	A			
Erosion (Control or Prevention)	A			
Chemicals	A			
Wildlife and Fisheries Habitat (Protection)	A			
Wastes	A			
Historical / Archaeological Sites	A			
Ecological Resources	A			
Fuel Storage	A			
Brush Disposal	A			
Restoration of Lands	A			
Permits	A			
Matters not Inconsistent	A			
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			

Explanatory Remarks -

Operation :

During this inspection it was observed that material was being stockpiled in the central location at km 251, please note that per Part "A" of your Land Use Permit indicates (Extraction, temporary stockpiling and hauling of granular material.)" this is to ensure other permit holders have an easy access with safe maneuverability into and out of their work areas. Further it was indicated in the Quarry Pit Development plan that no stock piling will occur at this site, as well under Land Use Permit part "A"(b). Further on this matter no contact to an inspector was made to stockpile or this stock pile was for INF O&M file.

It is the permit holders responsibility to ensure that the terms and conditions are



ENVIRONMENTAL INSPECTION REPORT

followed. Not only is this the permit holders responsibility, it is also their responsibility to plan ahead to ensure that delays may occur and a location should be provided for the stock piles ahead of time. It is recommended that material is to be removed from site.

MATTERS FOR FOLLOW UP

Stock piles are to be removed from site as this is a multi user source and safe maneuverability may be a risk.

N/A

Representative Signature

Inspector's Signature



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1



Figure 2

