



South Slave Region
41 Capital Drive #203
Hay River, NT X0E 1G2

Telephone: 867 874-6994
Fax: 867 874-2460

August 28, 2014

ProCore Drilling Ltd.
28076B Mackenzie Highway
Hay River, NT X0E 0R4

Attn: Darrell Dean

**RE: Land Use Permit M2013Q0017
QUARRY SITE - New
NWT Highway No. 5, Km 34.1 Site A & Site C**

Dear Mr. Dean,

An inspection of the above noted operation was conducted on August 12, 2014 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

Please note your quarry permit expired on July 17th, 2014. No further quarrying or removal of material is permitted until a quarry permit final plan has been received and verified by the Inspector and a new quarry permit is issued.

As per Condition 11 of your Quarry permit "Prior to the tenth day of each month, the Permittee shall submit a report to the Land Use Inspector at fax number (867) 874-2460, indicating the quantity of material quarried and the quantity of material removed from the site. Failure to submit the monthly report within indicated time frames may result in cancellation of this permit as per section 12 (5) of the regulations." Please ensure these reports are being sent to our office.

Thank you for your cooperation.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer
Department of Lands
South Slave Region

Cc: MVLWB
Charlene Coe, Land Use Advisor – Dept of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2019
Land Use Permit No.	M2013Q0017	Previous Inspection:	New
Quarrying Permit No.	2013QP0083	Inspection Date:	August 12, 2014
Contractor:		Subcontractor:	
Location(s) Inspected:	NWT Highway No. 5, Km 34.1 Site A & Site C		
Current Stage of Operation:			
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected			
	Pit			
Brush Disposal	A			
Chemicals	A			
Equipment as Approved (Type & Size)	A			
Erosion (Control or Prevention)	U			
Facilities	A			
Fuel Storage	U			
Location as Permitted	A			
Permits	A			
Restoration of Lands	A			
Time as Permitted	A			
Wastes	U			
Wildlife and Fisheries Habitat (Protection)	A			

Explanatory Remarks -

Please note that your quarry permit expired on July 17, 2014. No further quarrying is authorized until you complete your final quarry plan (Quarry Permit Condition 12) and apply and receive a valid quarry permit.

As per Condition 11 of your Quarry permit "Prior to the tenth day of each month, the Permittee shall submit a report to the Land Use Inspector at fax number (867)874-2460, indicating the quantity of material quarried and the quantity of material removed from the site. Failure to submit the monthly report within indicated time frames may result in cancellation of this permit as per section 12 (5) of the regulations." Please ensure these reports are being sent to our office.

The large stockpile of material must be sloped to a minimum of 2:1 horizontal/vertical ratio as per Condition 16 of your land use permit. The old dryer that is located at the west end of the pit (Site C) must be removed from federal lands and taken to an authorized facility for disposal (Condition 25).

It was noted during the inspection that the loader parked at Site C was leaking oil onto the ground. As per Condition 35 of your land use permit "All equipment that may be parked for two hours or more should have a haz-mat/drip tray under it or be sufficiently diapered. (Leaky equipment should be repaired immediately.)" Please ensure that the loader is repaired immediately and Condition 35 is being followed. All contaminated soil must be cleaned up and taken to an authorized facility for disposal (Condition 32 and 36).

All other aspects appeared satisfactory.

ORIGINAL SIGNED

Representative Signature

Inspector's Signature

Date:	August 12, 2014	Permit #:	M2013Q0017	Page No:	1
-------	-----------------	-----------	------------	----------	---

ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Stockpile must be sloped to a 2:1 horizontal/vertical ratio. Material has been removed from the stockpile recently.



Figure 2

Material has been removed recently from the west end of Site C. Note the old dryer to the right in the picture must be removed.



Figure 3

Loader parked near the stockpile at Site C.



Figure 4

Loader is leaking oil on to the ground. Haz-mat/drip trays are not being used and the loader is not diapered.

