



Telephone: 867 874-6994

Fax: 867 874-2460

July 4, 2018

ProCore Drilling Ltd.
28067B Mackenzie Highway
email: ddean@northwestel.net
Hay River, NT X0E 0R4

Attention: Darrel Dean

File Number	MV2013Q0017
Type of Operation	QUARRY SITE - New
Location	Km 34.1, NWT Highway No. 5, Sites A & C

Dear Mr. Dean,

An inspection of the above noted operation was conducted on June 20, 2018 by Resource Management Officers Jayda Robillard and Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the noted conditions in the report.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

ORIGINAL SIGNED

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: MVLWB
Regional Superintendent South Slave – GNWT Dept of Lands
Land Use Advisor North Slave – GNWT Dept of Lands



ENVIRONMENTAL INSPECTION REPORT

Permittee:	ProCore Drilling Ltd.	Permit Expiry Date:	May 21, 2019
Land Use Permit No.	MV2013Q0017	Previous Inspection:	October 26, 2017
Quarrying Permit No.	2017QP0025	Inspection Date:	June 20, 2018
Contractor:		Subcontractor:	
Location(s) Inspected:	Km 34.1, NWT Highway No. 5, Sites A & C		
Current Stage of Operation:	Quarrying has taken place at Site C this season.		
Program Modifications Approved:			

**Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable
“N/I” - Not Inspected**

Operating Condition	Aspect Inspected			
	Site A	Site C		
Erosion (Control or Prevention)	A	A *16		
Chemicals	A	A		
Wildlife and Fisheries Habitat (Protection)	A	A *23		
Wastes	A	A		
Historical / Archaeological Sites	A	A		
Fuel Storage	A	A		
Brush Disposal	A	A		
Restoration of Lands	A	A		
Location as Permitted	A	A		
Time as Permitted	A	A		
Permits	A	A		
Equipment as Approved (Type & Size)	A	A		
Facilities	A	A		

Explanatory Remarks -

Site A:

There was no sign of recent activity.

Site C:

There was no equipment in the pit at the time of inspection however quarrying has taken place at Site C this season under the authority of quarry permit #2017QP0025. Granular material has been removed from the large stockpile.

The Inspectors observed swallows nesting in the stockpile. No further material can be removed from this stockpile until the eggs have hatched and the birds have left the nests to avoid disturbing them in accordance with **Condition 23** of your LUP. Once the birds have left the nests, the stockpile should be contoured to a 2:1 horizontal/vertical slope (**Condition 16**) to avoid having the birds nest in the pile next year and potentially disrupting your operation.

Original signed by Jayda Robillard

Representative Signature

Inspector’s Signature

Date:	June 20, 2018	Permit #:	MV2013Q0017	Page No:	1
-------	---------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Site C: Large stockpile where quarrying has taken place this season.



Figure 2

Site C: Swallows nesting in the stockpile.





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Site A: No sign of recent activity.

