



Telephone: 867 874-6994

Fax: 867 874-2460

November 4, 2020

Rowe's Construction
25 Studney Drive
Hay River, NT X0E 0R6

Attention: Jack Rowe

File Number MV2015Q0022
Type of Operation QUARRY SITE - Existing
Location NWT Highway No. 1, Km 191.6

Dear Mr. Rowe,

An inspection of the above noted operation was conducted on August 07, 2020 by Resource Management Officer Jayda Robillard and Manager, Resource Management Rob Walker.

Enclosed is a copy of the Environmental Inspection Report. There were no environmental concerns noted at the time of inspection, however as a measure of public safety, the Inspector is requesting that Rowe's Construction place a berm around the two excavations on site. Alternatively, the sides of the excavations can be sloped to a 2:1 ratio as required by Condition 12 of your Land Use Permit.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard
Resource Management Officer II
Department of Lands
South Slave Region

CC: Mackenzie Valley Land and Water Board
Derise Rehm-Lepine, Superintendent South Slave – Dept of Lands
Charlene Coe, Land Use Advisor North Slave



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Rowe's Construction	Permit Expiry Date:	February 17, 2021
Land Use Permit No.	MV2015Q0022	Previous Inspection:	July 16, 2019
Quarrying Permit No.	20/0008	Inspection Date:	August 07, 2020
Contractor:		Subcontractor:	
Location(s) Inspected:	NWT Highway No. 1, Km 191.6		
Current Stage of Operation:	No sign of recent activity.		
Program Modifications Approved:			

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected
	Pit
Time as Permitted	A
Brush Disposal	A
Restoration of Lands	A
Permits	A
Equipment as Approved (Type & Size)	A
Location as Permitted	A
Matters not Inconsistent	A
Chemicals	A
Wildlife and Fisheries Habitat (Protection)	A
Facilities	A
Erosion (Control or Prevention)	A
Historical / Archaeological Sites	N/A
Wastes	A
Methods & Techniques	A
Fuel Storage	A

Explanatory Remarks -

There has been no activity in the pit this season. A small stockpile of granular material (quarry permit #2014QP0027) remains on site.

As seen in the attached photos, vegetation is starting to grow up making it difficult to see the two excavations on site. As a measure of public safety, the Inspector is requesting that Rowe's Construction place a berm around the two excavations on site. Alternatively, the sides of the excavations can be sloped to a 2:1 ratio as required by Condition 12 of your Land Use Permit.

No environmental concerns were noted at the time of inspection.

Representative Signature



Inspector's Signature

Date:	August 07, 2020	Permit #:	MV2015Q0022	Page No:	1
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

No sign of recent activity. One of the open excavations is barely visible in the background due to the vegetation.



Figure 2

Vegetation has reduced the visibility of the second excavation on site.

