



Department of Lands
Dehcho Region
P.O. Box 150
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205
Fax: 867-695-2615

September 9, 2021

Paramount Resources Ltd
Suite 2800, 421 - 7 Avenue SW
Calgary, AB T2P 4K9

Attention: Terence Hughes

File Number	MV2016A0010
Type of Operation	OIL AND GAS DRILLING - WELLSITE
Location	Well Sites I-02, F-36, O-35, N-01

Dear Terence Hughes,

An inspection of the above noted operation was conducted on August 26, 2021 by Manager, Resource Management Danielle Rogers, and Resource Management Officer II Andrew Lirette.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Lands
Dehcho Region

CC: Angela Love- Regulatory Specialist, MVLWB
Melinda Lenoir- Regional Superintendent, Department of Lands, Dehcho Region
Andrew Lirette- Resource Management Officer II, Department of Lands, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Paramount Resources Ltd	Permit Expiry Date:	October 04, 2021
Land Use Permit No.	MV2016A0010	Previous Inspection:	July 30, 2020
Quarrying Permit No.		Inspection Date:	August 26, 2021
Contractor:		Subcontractor:	
Location(s) Inspected:	Well Sites I-02, F-36, O-35, N-01		
Current Stage of Operation:	Reclamation/Remediation		
Program Modifications Approved:	N/A		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	Well Sites				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Lands inspected the well sites associated with the MV2016A0010 Land Use Permit on August 26, 2021. Aerial photographs and access to the locations were done using a helicopter.

I-02

The wellhead was still present on site. The two sumps were grown in and vegetation regrowth was established throughout the site. There was bare ground around the wellhead with some pooling water. Inspectors have no concerns with the I-02 well site and will continue to monitor the location.

F-36

The wellhead and riser were still present on site. Vegetation is established throughout the site. There was debris around the wellhead as well as a pile of debris on site. Inspectors have no concerns with the F-36 well site and will continue to monitor the location.



ENVIRONMENTAL INSPECTION REPORT

0-35

Vegetation was established throughout the site. There was sign in place where the wellhead was. Inspectors have no concerns with the 0-35 well site and will continue to monitor the location.

N-01

There was a sign in place where the wellhead used to be. Vegetation is established throughout the site. There were sumps on site holding water. Inspectors have no concerns with the N-01 well site and will continue to monitor the location.

Date:	August 26, 2021	Permit #:	MV2016A0010	Page No:	2
-------	-----------------	-----------	-------------	----------	---



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Aerial of I-02



Figure 2

Bare ground around I-02 wellhead





ENVIRONMENTAL INSPECTION REPORT

Figure 3
I-02 wellhead



Figure 4
Aerial of F-36





ENVIRONMENTAL INSPECTION REPORT

Figure 5
F-36 wellhead



Figure 6
Debris around F-36 wellhead





ENVIRONMENTAL INSPECTION REPORT

Figure 7

Pile of debris on F-36 well site



Figure 8

Riser on F-36 well site





ENVIRONMENTAL INSPECTION REPORT

Figure 9
Aerial of 0-35



Figure 10
0-35 sign





ENVIRONMENTAL INSPECTION REPORT

Figure 11
Aerial of N-01



Figure 12
N-01 sumps holding water

