



Telephone: 867 874-6994

Fax: 867 874-2460

January 6, 2022

Carter Industries Ltd.  
40 Studney Drive  
Hay River, NT X0E 0R6

**Attention: Shawn Carter**

**File Number** MV2015Q0003  
**Type of Operation** QUARRY SITE - Existing  
**Location** HR34-6, 9 and 12, Km 44.5, NWT Hwy No. 5

Dear Mr. Carter,

An inspection of the above noted operation was conducted on October 28, 2021 by Resource Management Officer Jayda Robillard and Manager, Resource Management Norm McCowan.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867 874-6994.

Sincerely,

Jayda Robillard  
Resource Management Officer III  
Department of Lands  
South Slave Region

CC: MVLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	Carter Industries Ltd.	<b>Permit Expiry Date:</b>	April 22, 2022
<b>Land Use Permit No.</b>	MV2015Q0003	<b>Previous Inspection:</b>	July 08, 2021
<b>Quarrying Permit No.</b>	20/0027	<b>Inspection Date:</b>	October 28, 2021
<b>Contractor:</b>		<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	HR34-6, 9 and 12, Km 44.5, NWT Hwy No. 5		
<b>Current Stage of Operation:</b>	Permittee has been removing granular material from existing stockpiles and pitrun material from the active face at HR34-6 under the authority of quarry permit #2020QP0027.		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	HR34				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Historical / Archaeological Sites	A				
Fuel Storage	U(24)				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

Explanatory Remarks -

HR34:

The Permittee has several large stockpiles of processed granular material in the HR34-6/9 area. Granular material has been removed from these stockpiles and pitrun has been removed from the active face on the northwest side of the pit under the authority of quarry permit #2021QP0027. **Although no spills or drips were observed during the inspection, the loader parked on site requires a drip tray as per Condition 24 of your land use permit.**

The Permittee has completed the initial clearing to the west edge of HR34-6. Brush disposal will be addressed at a later date. Access has been maintained to the west side of the HR34

Date:	October 28, 2021	Permit #:	MV2015Q0003	Page No:	1
-------	------------------	-----------	-------------	----------	---



### ENVIRONMENTAL INSPECTION REPORT

deposit.

Two large stockpiles of "Sanding Mat" and "Cement Gravel" remain at HR34-12.

No concerns were noted at the time of inspection.

\_\_\_\_\_  
Representative Signature

\_\_\_\_\_  
Inspector's Signature





## ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**

Facing south, west edge of the clearing at HR34-6.



**Figure 2**

Road along the north side of HR34-6 to the western portion of the deposit has been maintained.



**Figure 3**

North side of the clearing at HR34-6. Brush disposal will be completed at a later date.



**Figure 4**

HR34-6 - Stockpiles of processed granular material.



**Figure 5**

Facing northwest, road to western portion of HR34 deposit has been maintained.



**Figure 6**

Screener parked at HR34-6/9.







## ENVIRONMENTAL INSPECTION REPORT

**Figure 7**  
Loader parked at HR34-6.



**Figure 8**  
Loader onsite requires a drip tray.



**Figure 9**  
Active face at HR34-6.



**Figure 10**  
HR34-12 - Facing south



**Figure 11**  
HR34-12 - Large stockpiles of Cement Gravel and Sanding Mat remain on site.

