



Department of Environment and Climate Change
Dehcho Region
P.O.Box 150
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205
Fax: 867-695-2615

May 12, 2023

Nogha Enterprises Ltd.
PO Box 410
Fort Simpson, NT X0E 0N0

Attention: Carl Lafferty and Scott Gordon

File Number	MV2020Q0005
Type of Operation	QUARRY SITE - Existing
Location	HWY 1 KM 486.1

Dear Carl Lafferty and Scott Gordon,

An inspection of the above noted operation was conducted on May 09, 2023 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Environment & Climate
Change
Dehcho Region

CC: Tyree Mullaney- Regulatory Specialist, MVLWB
Kyle Christiansen- Acting Regional Land & Water Superintendent, Department of ECC, Dehcho
Christopher Penner- Lands Officer, Department of ECC, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Nogha Enterprises Ltd.	Permit Expiry Date:	September 06, 2025
Land Use Permit No.	MV2020Q0005	Previous Inspection:	May 24, 2022
Quarrying Permit No.	20/0009	Inspection Date:	May 09, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	HWY 1 KM 486.1		
Current Stage of Operation:	Ongoing		
Program Modifications Approved:	N/A		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	KM 486.1				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Environment and Climate Change conducted an inspection of Land Use Permit MV2020Q0005 on May 9, 2023.

There was one stockpile on site. The quarry face had the desired 2:1 ratio. There was an excavation area. Inspectors recommend placing markers (ie. pylons) at the entrance and the accessible side for safety purposes.

No equipment or fuel was present at the time of the inspection. There was evidence of other users in the quarry area.

The Inspectors have no major concerns and will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

Stockpile on site



Figure 2

View of active face





ENVIRONMENTAL INSPECTION REPORT

Figure 3

Active excavation area- no markers



Figure 4

Entrance to excavation- no markers

