



Department of Environment and Climate Change
Land and Water Division- Dehcho
P.O Box 150
Fort Simpson, NT X0E 0N0

Telephone: 867-695-2626 ext. 205
Fax: 867-695-2615

June 5, 2023

Imperial Oil Limited
PO Box 2480 Station M
505 Quarry Park Blvd SE
Calgary, AB T2C 5N1

Attention: Esther Choi

File Number	MV2021X0019
Type of Operation	MISC.
Location	Wellsite

Dear Esther Choi,

An inspection of the above noted operation was conducted on May 18, 2023 by Manager, Resource Management Danielle Rogers and Lands Officer Christopher Penner.

Enclosed is a copy of the Environmental Inspection Report.

If you have any questions, please contact me at 867-695-2626 ext. 205.

Sincerely,

Danielle Rogers
Manager, Resource Management
Department of Environment and
Climate Change

CC: Tyree Mullaney- Regulatory Specialist, MVLWB
Laurie Nadia- Regional Land and Water Superintendent, Department of ECC, Dehcho Region
Christopher Penner- Lands Officer, Department of ECC, Dehcho Region



ENVIRONMENTAL INSPECTION REPORT

Permittee:	Imperial Oil Limited	Permit Expiry Date:	November 11, 2026
Land Use Permit No.	MV2021X0019	Previous Inspection:	January 31, 2023
Quarrying Permit No.		Inspection Date:	May 18, 2023
Contractor:		Subcontractor:	
Location(s) Inspected:	Wellsite		
Current Stage of Operation:	Monitoring		
Program Modifications Approved:	N/A		

Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected

Operating Condition	Aspect Inspected				
	B-48				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Facilities	A				
Erosion (Control or Prevention)	A				
Chemicals	A				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Brush Disposal	A				
Restoration of Lands	A				
Permits	A				

Explanatory Remarks -

Inspectors from the Department of Environment and Climate Change conducted an inspection of the B-48 wellsite associated with the MV2021X0019LUP on May 18, 2023, via helicopter.

The B-48 wellsite had no ponding of water around the sign at the time of the inspection. There was water in a natural depression on site. No rutting was noted throughout the wellsite.

Inspectors will continue to monitor.



ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

Figure 1

View of B-48 Wellsite



Figure 2

View of B-48 Wellsite

