

April 11, 2023

Mr. Mason Mantla Chair  
Wek'èezhii Land and Water Board  
#1, 4905-48th Street  
Yellowknife, NT  
X1A 3S3

Jamie Steele  
North Slave Regional Office  
Department of Lands  
Government of the Northwest Territories  
#16 Yellowknife Airport  
Yellowknife, NT  
X1A 3T2

**Subject: W2016D0003: Spill 2023141 Report**

Pursuant to Part C Condition 18© of Land Use Permit W2016D0003, Arctic Canadian Diamond Company Ltd. (Arctic) is providing a detailed spill report on Spill 2023141 which occurred on April 8, 2023, inside Sable Pit.

**Summary**

At 12:30 AM, on April 8, 2023, the fitting for the track tensioner of Shovel 2569 (6060) came loose which resulted in a hydraulic oil spill of 250L. The spill covered a 2m<sup>2</sup> area.

The location of the spill was inside Sable Pit area.

Lat 64°51'37.34"N  
Long 110°30'40.82"W

**Root Cause**

Due to cold temperature conditions and were the fitting for the track tensioner from 2569 Shovel (6060) came loose and caused the hydraulic oil spill.

**Immediate Action Taken**

The 2m<sup>2</sup> contaminated area was removed and transported to the Sable contaminated soil bin and will be properly disposed of by waste management department.



**Arctic Canadian Diamond Company Ltd.**

900-606 4 Street SW (403) 910-1933  
Calgary, Alberta T2P 1T1 (403) 910-1934 fax

**Follow Up Action Taken**

Surface mining team lead ensured all the spill was properly removed.

We trust this report is clear and informative. If you have any questions or comments, please contact the undersigned at [Tania.robaille@arcticcanadian.ca](mailto:Tania.robaille@arcticcanadian.ca) or (867) 880-4400 ext. 2059.

Yours Sincerely,

A handwritten signature in blue ink, appearing to read "Tania", followed by a horizontal line.

Tania Robaille  
Environmental Specialist  
Arctic Canadian Diamond Company Ltd.