



Rio Tinto Exploration Canada Inc
1300 Walsh St. W
Thunder Bay, ON P7E 4X4
T + 1 807 473 5558 F + 1 807 473 5660

August 4th, 2020

Kassandra DeFrancis
Anneli Jokela
Wek'eezhii Land and Water Board
#1 – 4905 48th Street
Yellowknife, NT, X1A 3S3

Email: kdefrancis@wlb.ca

Email: ajokela@wlb.ca

Dear Ms. Francis & Ms. Jokela:

Re: RTX Exploration Drilling at Diavik Progress Report - July

Following Condition 8 of the Land Use Permit W2017C0002, namely;

The Permittee shall submit a progress report to the Inspector and the Board every month during which there is an active drill program.

we wish to inform you of the progress of our drilling program.

Work on our exploration program re-started up the month of July using the Downing Duralite 250B drill. During this period, six drill holes were completed. The following table is a breakdown of the collar coordinates (NAD83 UTM 12N), dip, azimuth and drilling distances that were completed on each hole. Attached at the end of this letter is a map showing the relative location between the holes and with the mine site.

HOLEID	X_NAD83	Y_NAD83	Total Depth	Azimuth	Dip	Dates Drilled
T29W-01	535133	7145738	109.5m	302	45	July 17 - 19
C1042-03	536056	7145234	102 m	145	45	July 19 - 22
C49N-01	533249	7142433	87 m	180	45	July 22 - 23
C422-01	532187	7139414	90 m	335	60	July 24 - 25
C422-02	532046	7139626	154.5 m	12	45	July 25 - 27
C49W-01	533067	7141913	130.5 m	45	45	July 28 - 31

Mobilization from Diavik to each target location was completed using Acasta HeliFlight's BH407 helicopter.

RioTinto

Should you have any questions or concerns, please do not hesitate to be in touch.

Sincerely,

A handwritten signature in black ink, appearing to be 'E. Lyon', written in a cursive style.

Eileen Lyon
Principal I Geoscientist
Project Manager for Diavik Brownfields




Figure 1: Plan map showing the location of the completed drillholes in July in relation to Diavik diamond mine.