



May 19<sup>th</sup>, 2024

Mr. Mason Mantla Chair  
Wek'èezhii Land and Water Board  
#1, 4905-48th Street  
Yellowknife, NT  
X1A 3S3

Jamie Steele  
North Slave Regional Office  
Department of Lands  
Government of the Northwest Territories  
#16 Yellowknife Airport  
Yellowknife, NT  
X1A 3T2

**RE: W2022L2-0001 – Spill-2024111**

Pursuant to Part I Conditions Applying to Contingency Planning, Burgundy Diamond Mines Ltd. (Burgundy) is providing a detailed spill report on Spill-2024111 which occurred April 19th, 2024, at 02:00.

**Summary**

At 02:00 on April 19<sup>th</sup> an employee noticed a 100L diesel spill underneath a parked lube truck at the Ekati truck shop laydown

**Root Cause**

The root cause was a fuel line connection failure causing a leak.

**Immediate Action Taken**

The employee noticed the spill, located the source, and stopped the leak. The team lead was notified, and the truck was moved to initiate cleanup.

**Follow Up Action Taken**

The contaminated material was scraped up and disposed of directly at the landfarm and drivers were reminded to check connections during their walk around.



We trust this report is clear and informative. If you have any questions or comments, please contact the undersigned at [landon.murphy@burgundydiamonds.com](mailto:landon.murphy@burgundydiamonds.com) or (867) 880-4400 ext. 2293.

Sincerely,

Landon Murphy  
Advisor – Environmental Operations  
Burgundy Diamond Mines

*CC: Tania Robitaille – Advisor – Environmental Operations  
William Liu – Manager, Environmental Reporting & Permitting  
Richard Ehlert – Environment Team Leader*

Record # HSE RDC ENV 1988  
Document Owner: Environment Department  
Date: 19-May-24