



Telephone: 867-777-8907

Fax: 867-777-2090

July 14, 2021

GNWT Department of Infrastructure  
Bag Service #1, 106 Veterans Way  
Inuvik, NT X0E 0T0

**Attention: Mosiul Alam**

**File Number** G20H006  
**Type of Operation** CAMPS - < 50 Man Camp  
**Location** Km 14.2 James Creek

Dear Mosiul Alam,

An inspection of the above noted operation was conducted on July 13, 2021 by Resource Management Officer II Herbert Allen.

Enclosed is a copy of the Environmental Inspection Report. Please refer to the unacceptable and noted conditions in the general comments section of this report. Your attention to this matter is appreciated.

If you have any questions, please contact me at 867-777-8907.

Sincerely,

Herbert Allen  
Resource Management Officer II  
Department of Lands  
Beaufort Delta Region

CC:

Dan Carmichael, Regional Superintendent, Department of Lands, Beaufort Delta Region  
GLWB



## ENVIRONMENTAL INSPECTION REPORT

<b>Permittee:</b>	GNWT Department of Infrastructure	<b>Permit Expiry Date:</b>	August 05, 2021
<b>Land Use Permit No.</b>	G20H006	<b>Previous Inspection:</b>	June 23, 2021
<b>Quarrying Permit No.</b>	68	<b>Inspection Date:</b>	July 13, 2021
<b>Contractor:</b>	L.J.'s Septic Services & Contracting Ltd.	<b>Subcontractor:</b>	
<b>Location(s) Inspected:</b>	Km 14.2 James Creek		
<b>Current Stage of Operation:</b>	On-going		
<b>Program Modifications Approved:</b>			

**Condition of Operation "A" - Acceptable "U" - Unacceptable "N/A" - Not Applicable "N/I" - Not Inspected**

Operating Condition	Aspect Inspected				
	<b>James Creek Km 14.2</b>				
Location as Permitted	A				
Time as Permitted	A				
Equipment as Approved (Type & Size)	A				
Methods & Techniques	A				
Chemicals	U				
Wildlife and Fisheries Habitat (Protection)	A				
Wastes	A				
Fuel Storage	A				
Restoration of Lands	A				
Permits	A				
Matters not Inconsistent	A				
Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A				

**Explanatory Remarks -**

James Creek Km 14.2:


During the inspection on July 13, 2021 at the James Creek site there was only 1 concern observed by the inspector.

There were a few spills on the ground at the west side of the site that was mentioned in the last inspection report dated June 23, 2021 that was not cleaned up.

At the time of this inspection one of the workers Joey Blake was at the site, I showed him the spills and he indicated that he will have the spills cleaned up immediately.

The rest of the site looks in good order.

  
\_\_\_\_\_  
Representative Signature

  
\_\_\_\_\_  
Inspector's Signature



# ENVIRONMENTAL INSPECTION REPORT

Inspection Images:

**Figure 1**



**Figure 2**





# ENVIRONMENTAL INSPECTION REPORT

Figure 3



Figure 4

