



Alastair Still  
507140 NWT Ltd. (GoldMining Inc.)  
1830-1030 West George St.  
Vancouver, BC V6E 2Y3

September 14<sup>th</sup> 2023

Mineral Exploration Ormsby and Nicholas Lake Declines, including a camp.

**RE: Land Use Permit MV MV2018C0021 – 507140 N.W.T Ltd. Goldmining Inc.**

Dear Mr. Still,

An inspection of Discovery Mine Site owned and operated by GoldMining Inc. was completed by Resource Management Officer Tim Morton on August 3<sup>rd</sup> 2023. The inspection was conducted to ensure compliance with the terms and conditions of the land use permit and approved management plans.

The attached inspection report contains details and photos that were taken during the inspection.

If you have any questions or concerns please contact me at (867) 669-2442.

Thank you,

Tim Morton  
Resource Management Officer (Inspector)  
Resource and Land Management  
Crown-Indigenous Relations and Northern Affairs Canada

cc. MVLWB – via email  
CIRNAC Resource and Land Management – via email



**INSPECTION DATE – August 3<sup>rd</sup> 2023**

**ENVIRONMENTAL INSPECTION REPORT (MV2018C0021)**

Permittee:	GoldMining Inc.	October 17 <sup>th</sup> , 2023	June 1 <sup>st</sup> 2022
------------	-----------------	---------------------------------	---------------------------

Permit Expiry Date Last Previous

Inspection

Land Use Permit No.	MV2018C0021		
Quarrying Permit No.	N/A		
Contractor:	N/A	Subcontractor:	N/A

Location(s) Inspected:	Camp, Fuel Storage, Portal Area, Core Storage, and Airstrip
------------------------	---

Current Stage of Operation:	Non-Operational
-----------------------------	-----------------

Program Modifications Approved:	None
---------------------------------	------

Condition of Operation “A” - Acceptable “U” - Unacceptable “N/A” - Not Applicable “N/I” - Not Inspected

	Operating Condition	Aspect Inspected			
		Permit Area			
A	Location as Permitted	A			
B	Timing as Permitted	A			
C	Equipment as Approved (Type & Size )	A			
D	Methods & Techniques	A			
E	Facilities	A			
F	Erosion (Control or Prevention )	A			
G	Chemicals	A			
H	Wildlife and Fisheries Habitat (Protection )	A			
I	Wastes/Sewage	A			
J	Historical / Archaeological Sites	A			
K	Ecological Resources	A			
L	Security Deposit	A			
M	Fuel Storage	A*			c#74
N	Brush Disposal	A			
O	Restoration of Lands	A			
P	Permits	A			
Q	Biological/Physical	A			
R	Sections 8 to 12 / 14 to 16 M.V.L.U.R.	A			
S	Quarrying Methods	N/A			



## ENVIRONMENTAL INSPECTION REPORT Pg. 2 (Continued)

Date:	August 3 <sup>rd</sup> 2023	Permit #:	MC2018C0021
-------	-----------------------------	-----------	-------------

### Explanatory Remarks:

An inspection of Discovery Mine Site owned and operated by GoldMining Inc. was completed by Resource Management Officer Tim Morton on August 3<sup>rd</sup> 2023. The inspection was conducted to ensure compliance with the terms and conditions of the land use permit and approved management plans.

The site was unmanned and showed no recent activity. All of the buildings have been secured and no signs of unauthorized entry were observed during the inspection (Photo #7 & #8). There was a minor hydrocarbon leak from the grader discovered during the inspection (Photo #6). It is strongly recommended that all vehicles and machinery be serviced to avoid any future releases.

The Permittee has recently applied for a two year extension to the land use permit which if granted will extend the expiry date to October 17<sup>th</sup> 2025.

The Inspector would like to discuss the future operation of the project and to discuss what plans the Permittee has for the site in 2024 season.

Original Signed

---

Inspectors Signature



**Photo #1: Overview of the decline area and surrounding infrastructure**



**Photo #2: Overview of the camp and fuel storage**



**Photo #3: Overview of the airstrip**



**Photo #4: Vegetation growing on the airstrip**



**Photo #5: Site waste stored within secondary containment and covered with a tarp**



**Photo #6: Hydrocarbon leak under the grader stored near the camp**



**Photo #7: Camp buildings continue to be secure**



**Photo #8: Portal shop continues to be secure**