

Incident #	INC-2019-008-HUS-OA-2018-002	
Incident occurred on:	March 5, 2019	
OA/ACW #:	ACW-2018-002	
Operator:	Husky Oil Ltd.	
Location:	Slater River – N-09	
Summary of incident:	Over pressurized well – Jacking of tubing – No Injury	
Incident reported to OROGO by the operator on:	March 5, 2019	
Incident reported to NT-NU Spill Line (if required) on:	N/A	
Operator Follow-up Investigation Report:	Due: March 26, 2019 Received: March 26, 2019	
Status:	<p>Mar. 5, 2019: Well was over pressurized by pump causing 1 length of tubing to be jacked out of the well bore.</p> <p>Operations were terminated.</p> <p>Move forward plan was developed by Husky and was reviewed by OROGO.</p> <p>Plan executed and OROGO provided approval to commence operations.</p> <p>March 26, 2019: Investigation report received and reviewed.</p> <p>OROGO reviewed the report and is satisfied with the corrective actions identified to mitigate similar incidents of this nature in the future.</p> <p>Incident File Closed.</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.