

|  |   |  |
|--|---|--|
| <b>Incident #</b>  | INC-2019-003-HUS-OA-2018-002  |  |
| <b>Incident occurred on:</b>                                   | February 13, 2019   |  |
| <b>OA/ACW #:</b>   | ACW-2018-003  |  |
| <b>Operator:</b>   | Husky Oil Ltd.  |  |
| <b>Location:</b>   | Slater River – H-64   |  |
| <b>Summary of incident:</b>                                    | 2" steam line rupture – No Injuries   |  |
| <b>Incident reported to OROGO by the operator on:</b>          | February 13, 2019   |  |
| <b>Incident reported to NT-NU Spill Line (if required) on:</b> | N/A   |  |
| <b>Operator Follow-up Investigation Report:</b>                | Due: Feb. 15, 2019<br>Received: Feb. 15, 2019   |  |
| <b>Status:</b>   | <p><b>Feb. 13, 2019:</b><br/>2" steam line ruptures</p> <p>Repairs made</p> <p>OROGO approved commencement of operations.</p> <p><b>Feb. 15, 2019</b><br/>Summary report was sent to OROGO for review.</p> <p>No further action required – Incident closed.</p> |  |
| <b>Completed By:</b>   | Michael Martin – Safety Officer   |  |

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.