

Incident #	INC-2019-005-HUS-OA-2018-002	
Incident occurred on:	February 16, 2019	
OA/ACW #:	ACW-2018-003	
Operator:	Husky Oil Ltd.	
Location:	Slater River – H-64	
Summary of incident:	Injured Worker – Struck by low pressure hose	
Incident reported to OROGO by the operator on:		February 16, 2019
Incident reported to NT-NU Spill Line (if required) on:		N/A
Operator Follow-up Investigation Report:		Due: Not Determined Received: Feb. 17, 2019
Status:	<p>Feb. 16, 2019: Dry cement transfer hose became disconnected and struck a worker.</p> <p>Worker assessed by medic on site.</p> <p>OROGO reported incident to WSCC.</p> <p>WSCC regulatory lead.</p> <p>Feb. 17, 2019: OROGO received incident summary from Husky.</p> <p>No further action required by OROGO.</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.