

Incident #	INC-2020-001-PAR-OA-2018-004	
Incident occurred on:	February 10, 2020	
OA/ACW #:	ACW-2018-009	
Operator:	Paramount Resources Ltd.	
Location:	Bovie J-76	
Summary of incident:	Seal failure on annual preventer	
Incident reported to OROGO by the operator on:	February 11, 2020	
Incident reported to NT-NU Spill Line (if required) on:	N/A	
Operator Follow-up Investigation Report:	Due: Mar. 2, 2020 Received:	
Status:	<p>Feb. 10, 2020: It was identified, by site staff, that a seal was faulty on the annular preventer when a leak was detected through the “tattle tale hole”. At no time was the well unsecured.</p> <p>The operations were shut down and the well left secured.</p> <p>Feb 11, 2020: The annular preventer was removed and a replacement annular preventer installed.</p> <p>Certifications of the replacement annular preventer were provided to OROGO to verify it was in proper working order.</p> <p>Feb 12,2020: Abandonment operations of the well resumed.</p> <p>Follow-up investigation report due on or before March 2, 2020</p>	
Completed By:	Michael Martin – Safety Officer	

This Report is subject to disclosure pursuant to paragraph 91(8)(h) of the *Petroleum Resources Act*.

If you would like this information in another official language, contact us at (867) 767-9097.