



NWT OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS

Office of the Regulator of Oil and Gas Operations

P.O. Box 1320, Yellowknife, NT X1A 2L9

Tel: 867-767-9097 • Fax: 867-920-0798 • Web: [www.oro.gov.nt.ca](http://www.oro.gov.nt.ca)

Courier Address: 4th floor, 5201 – 50th Avenue, Yellowknife, NT X1A 3S9

Ken Nikiforuk, Operations Consultant  
Strategic Oil and Gas Ltd.  
C/O Alvarez & Marsal Canada ULC  
SUITE 1100, 250 - 6th AVE SW  
CALGARY AB T2P 3H7

July 20, 2021

Dear Ken Nikiforuk:

**Information Request No. 1:**  
**Application to Abandon the Cameron N-28 Well (ACW-2021-N-28-WID1753)**

On July 6, 2021, the Office of the Regulator of Oil and Gas Operations (OROGO) received a well abandonment program from Strategic Oil and Gas Ltd. (Strategic) for the Cameron N-28 well (WID1753) well.

OROGO has reviewed the information provided by Strategic and requires additional information in order to complete its review of Strategic's application to abandon the N-28 well, as set out in the attached Information Request No. 1.

Please send your written responses and any associated correspondence to Peter Lennie-Misgeld, Senior Advisor, Legislation and Policy at [oro.gov.nt.ca](mailto:oro.gov.nt.ca), or through OROGO's secure file transfer site, on or before 4:00 p.m. on August 9, 2021.

If you are unable to respond within this timeframe or have any questions, please contact OROGO at (867) 767-9097 or by email at [oro.gov.nt.ca](mailto:oro.gov.nt.ca).

Sincerely,

Pauline de Jong  
Regulator

Encl. Information Request No. 1

c Duncan MacRae, Director, Alvarez & Marsal Canada ULC

**Strategic Oil and Gas Ltd.**  
**Application for an Authorization to Alter the Condition of a Well**  
**Cameron N-28 Well (ACW-2021-SOG-N-28-WID1753)**  
**Information Request No. 1**

**1.1 Wellbore Abandonment Program - Liner Abandonment**

**PREAMBLE:**

The well abandonment program submitted by Strategic on July 6, 2021 does not address the abandonment of the liner (Top 732 mKB) and the proposed wellbore diagram does not indicate the presence of the liner.

Section 6A of the *Well Suspension and Abandonment Guidelines and Interpretation Notes* (Guidelines) requires that, following abandonment of all completed intervals, the operator abandon the liner top before surface abandonment.

**REQUEST:**

Please submit an updated well abandonment program, as one complete consolidated document, that contains the following information:

- Procedures that include the abandonment of the liner top as per section 6A of the Guidelines; and
- An updated proposed wellbore diagram that accurately depicts the downhole configuration of the well upon abandonment.