



NWT OFFICE OF THE REGULATOR OF OIL AND GAS OPERATIONS

Office of the Regulator of Oil and Gas Operations

P.O. Box 1320, Yellowknife, NT X1A 2L9

Tel: 867-767-9097 • Fax: 867-920-0798 • Web: [www.oro.go.gov.nt.ca](http://www.oro.go.gov.nt.ca)

Courier Address: 4th floor, 5201 – 50th Avenue, Yellowknife, NT X1A 3S9

John Hawkins  
Director, Asset Management  
Paramount Resources Ltd.  
SUITE 2800, 421 – 7 AVE SW  
CALGARY AB T2P 4K9

August 15, 2022

Dear John Hawkins:

**Information Request No. 1:  
Liard 2K-29 Well Abandonment (ACW-2022-PAR-2K-29-WID1980)**

On August 15, 2022, the Office of the Regulator of Oil and Gas Operations (OROGO) received a complete application to Alter the Condition of a Well (ACW) from Paramount Resources Ltd. (Paramount) for the abandonment of the Liard 2K-29 well (WID 1980) in the Fort Liard area of the Northwest Territories.

OROGO has reviewed the information provided by Paramount and requires additional information to complete its review of Paramount's ACW application, as set out in the attached Information Request No. 1.

Please send your written responses and any associated correspondence to OROGO at [oro.go@gov.nt.ca](mailto:oro.go@gov.nt.ca) or through OROGO's secure file transfer site, on or before 4:00 pm on August 29, 2022. If you are unable to respond within this timeframe or have any questions, please contact OROGO at 867-767-9097 or by email at [oro.go@gov.nt.ca](mailto:oro.go@gov.nt.ca).

Sincerely,

Pauline de Jong  
Regulator

Encl. Information Request No. 1

**Information Request No. 1**  
**Liard 2K-29 Well Abandonment**  
**ACW-2022-PAR-2K-29-WID1980**

**1.1 Shallow Wellbore Plug**

**Preamble:**

The March 24, 2008 wellbore diagram submitted with Paramount's application shows a permanent bridge plug at 50 mKB. In April 2021, the Chief Safety Officer issued a Safety Bulletin on shallow wellbore plugs (OROGO-SB-01). The Safety Bulletin sets out the requirements for operations on wells with known or suspected shallow wellbore plugs. Paramount's proposed well abandonment program does not meet the requirements of OROGO-SB-01.

**Request:**

Submit an updated well abandonment program that meets the requirements of OROGO-SB-01.

**1.2 Abandoned Well Marker**

**Preamble:**

The abandoned well marker diagram included with Paramount's proposed well abandonment program does not reflect the changes made in the revised *Well Suspension and Abandonment Guidelines and Interpretation Notes* (Guidelines), issued in May 2022.

**Request:**

Submit an updated abandonment program that includes the abandoned well marker requirements found in section 6E of the May 2022 Guidelines.