

## WELLSITE SUMMARY INSPECTION REPORT

Well/Facility Name:	H-58/Cameron Hills	Operator:	Strategic Oil and Gas Ltd.
Location of Inspection:	Cameron Hills Production Field	Access method:	Helicopter – Great Slave Helicopters
Site Contractor:	None	Status:	Compliant Suspended – Production Well
Approval Info	OA-2018-003	WID:	1975
Date of Inspection	12/SEP/2019	H2S Site:	Yes

### Summary of Inspection

<b>Activity on site</b>	Gas migration testing and annual well inspections conducted by GChem (Contractor)		
<b>Conditions</b>	<b>Satisfactory (Y/N)</b>	<b>Comments</b>	
Site Access	Y		
Well Head Access	N	One well head valve not secured. (Photo #2) All well head valves must be secured to prevent unauthorized operation.	
Signage	Y		
General Housekeeping	Y		
SCV Open and dead	Y	0 Bubbles in 10 min at SCV.	

#### **Additional Site Hazards:**

Potential of H2S Gas exposure, personal monitors worn by inspectors.  
Signs of wildlife (tracks and scat)

#### **Comments and Summary:**

OROGO Inspection Team: Brian Heppelle (Chief Safety Officer), Pauline de Jong (Chief Conservation Officer) and Michael Martin (Safety Officer).

#### **Documents Requested/ Collected:**

Photos and notes taken on site.

**Inspection conducted under the authority of the Oil & Gas Operations Act (OGOA) and associated regulations.**

Michael Martin S-004 / Brian Heppelle S-001/Pauline de Jong C-002

Inspected By



Signature of OROGO Chief Safety Officer

2019-12-20

Date Signed



Photo # 1: Wellhead



Photo #2: One well head valve not secured. All well head valves must be secured to prevent unauthorized operation